

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources
CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
May 27, 2004

RECEIVED

MAR 18 2010

HOBBSCOCD

WELL API NO.	30-025-28645
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	NM BG SL NCT-2
8. Well number	4
9. OGRID Number	213190
10. Pool name or Wildcat	Saunders Permo Upper Penn

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator
Crown Quest Operating, L.L.C.

3. Address of Operator
303 Veterans Airpark Ste. 5100 Midland, TX 79710

4. Well Location
Unit Letter B : 990 feet from the North line and 2309 feet from the East line
Section 16 Township 14-S Range 33-E NMPM County Lea

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
4,225 GR

Pit or Below-grade Tank Application ☒ or Closure ☐

Pit type STEEL Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water N/A

Pit Liner Thickness: STEEL mil Below-Grade Tank: Volume _____ bbls: Construction Material STEEL

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 1) Circulated hole w/ 225 bbl of MLF
- 2) 3/10/10 Set 5 1/2" CIBP @ 9,727'
- 3) 3/11/10 Spot 35sx cmt @ 9,727' - 9,433'. Spot 25sx cmt @ 7,761' - 7,585'. Spot 35sx cmt @ 7,026' - Tag @ 6,685'
3/12/10 Spot 25sx cmt @ 5,564' - 5,311'. Spot 50sx cmt @ 4,278' - Tag @ 3,784'. Spot 45sx cmt @ 3,200' - 2,745'.
- 4) Spot 30sx cmt @ 2,635' - 2,332'. Spot 40sx cmt @ 1,767' - 1,362'. Spot 60sx cmt @ 620' - surface.

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Randall Miner TITLE Area Manager DATE 3/17/2010

Type or print name Randall Miner

For State Use Only

APPROVED BY: [Signature] TITLE STAFF MGR DATE 3-18-10

Conditions of Approval (if any):

CONDITIONS OF PA APPROVAL: Approved as to plugging of the Well Bore. Liability under bond is retained until surface restoration is completed. OCD Hobbs office needs C-103 "Check Off List for Surface Inspection".