

RECEIVED

Form 3160-3
(August 2009)

MAR 18 2010

HOBBSDOCD

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTNew Mexico Oil Conservation Division, District I
1625 N. French Drive
Hobbs, NM 88240FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease/Serial No.

NM15015B

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well☐ Gas Well☐ Other

2. Name of Operator

Cano Petro of New Mexico, Inc.

3a. Address

801 Cherry Street Suite 3200 Fort Worth, TX 76102

3b. Phone No. (include area code)

817-698-0900

7. If Unit of CA/Agreement, Name and/or No.
Oakson B Federal

8. Well Name and No.

3

9. API Well No.

30-005-20682

10. Field and Pool or Exploratory Area

Tom Tom; San Andres

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

C-33-07S-31E 660 FNL 1980 FWL

11. Country or Parish, State

Chaves, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent☐ Acidize☐ Deepen☐ Production (Start/Resume)☐ Water Shut-Off☐ Alter Casing☐ Fracture Treat☐ Reclamation☐ Well Integrity☒ Subsequent Report☐ Casing Repair☐ New Construction☐ Recomplete☒ Other ~~Return to Production~~☐ Final Abandonment Notice☐ Change Plans☐ Plug and Abandon☐ Temporarily Abandon☐ Water Disposal

Workover

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

7/1/2009: MIRU pulling unit and RIH w/ sinker bar on end of sand line. Tagged at 4000' and POOH. Csg swabbed 6 BF, trace oil. Started to RIH w/ 2-3/8" tubing

7/2/2009: RIH w/ rest of tubing and set sleps. Bottom of tubing at 3922'

8/26/2009: Welded on new bell nipple on wellhead. Started to RIH w/ rods and 1.5" insert pump

8/27/2009: RIH w/ rest of rods. Spaced out and hung on and rigged down. Started pumping on 9/1/2009. Made 1 BO and 44 BW in first 24 hours.

Accepted For Record Only! Approval
Subject To Returning Well To Continuous
Production And Keeping Well On Continuous
Production Or Plugging Well With An
Approved Plugging Program!

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Collin Strawn

Title Engineer

Signature

Date 01/27/2010

ACCEPTED FOR RECORD

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

/S/ DAVID R. GLASS

FEB 9 2010

PETROLEUM ENGINEER

Title

Date

MAR 19 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

ROSWELL FIELD OFFICE

Title 18 U.S.C. Section 1001 and Title 43-U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)