

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N French Dr, Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
RECEIVED  
APR 01 2010  
HOBBS  
CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-103  
June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR, USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)		WELL API NO. 30-025-29780
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Mack Energy Corporation		6. State Oil & Gas Lease No. VO-5232
3. Address of Operator P.O. Box 960 Artesia, NM 88210		7. Lease Name or Unit Agreement Name Cherry State
4. Well Location Unit Letter <u>E</u> <u>1980</u> feet from the <u>North</u> line and <u>660</u> feet from the <u>West</u> line Section <u>9</u> Township <u>16S</u> Range <u>32E</u> NMPM County <u>Lea</u>		8. Well Number 1
11. Elevation (Show whether DR, RKB, RT, GR etc.) 4345' GR		9. OGRID Number 013837
		10. Pool Name or Wildcat Anderson Ranch; Wolfcamp, West

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIALWORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Place in T & A Status ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

3/25/2010 MIRU tried to unset pkr. wouldn't turn loose, get Rotary to free point and cut off @ 9410'.  
3/26/2010 Lay down tbg.  
3/29/2010 Tagged cut off tbg @ 9410', POH. Set CIBP @ 9392' w/35' cement cap.  
3/30/2010 Set packer and test @ 3881', held. Squeeze perms @ 3361'-3651' w/200 sx Class C neat and 2% Cacl. Shut in.  
3/31/2010 RIH w/8-4 3/4" DC's and 6 1/8" bit, tagged cement @ 3180' and drilled out.  
4/1/2010 RU truck test casing to 500# holding. Circ. hole w/2% KCL & laydown tbg. Flange wellhead up & SD. T & A well.  
Chart attached.

This Approval of Temporary  
Abandonment Expires 4-1-2015

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 4/6/10

Type or print name Jerry W. Sherrell E-mail address: jerrys@mackenergycorp.com PHONE: (575)748-1288

For State Use Only

APPROVED BY [Signature] TITLE STAFF MGR DATE 4-8-10  
Conditions of Approval (if any):

