Form 3160-5 (April 2005)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0137
Expires: March 31, 2007

5. Lease Serial No

NM 13430

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

		l		
SUBMIT IN TRIPLICATE - Other instructions on	reverse side.	7. If Unit or CA, Ag	greement, Name and/or No.	
1. Type of Well  Gas  Gas				
X Well Well Other		8. Well Name an	d No.	
		∫ Lea 21, 7406 J	V-S #4Y /	
2. Name of Operator		0	<u> </u>	
FULFER OIL & CATTLE LLC		9. API Well No. 30-025-27207		
3a. Address 3b. Phone N	lo. (include area code)	30 023 27207	<b>✓</b>	
P.O. BOX 1224, JAL, NM 88252 575-392-3	3575		I, or Exploratory Area line; Tan-Yates-7R-QU 🗸	
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description)			,	
990' FSL & 1650' FEL /		11. County or Par	ish, State	
UL O, Section 21, T-26S, R-36E   √		Lea Co., NM		
12. CHECK APPROPRIATE BOX(s) TO INDICATE NAT	URE OF NOTICE	, REPORT, OR	OTHER DATA	
TYPE OF SUBMISSION TYPE OF ACTI	ON			
Acidize Deepen	X Pro	duction (Start/Resume)	Water Shut-Off	
Notice of Intent Alter Casing Fracture	Treat Rec	lamation	Well Integrity	
X Subsequent Report Casing Repair New Con	nstruction Rec	omplete	Other	
Final Abandonment Notice Change Plans Plug and	Final Abandonment Notice Change Plans Plug and Abandon Temporarily Abandon			
Convert to Injection Plug Bac	ck Wa	er Disposal		
		<del></del>	. l . d . C TC-l	
Describe Proposed or Completed Operation Clearly state all pertinent details, including estito deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the opera	and true vertical depths of all p ent reports shall be filed within 160-4 shall be filed once testin	ertinent markers and zone 30 days following comple g has been completed Fi	es Attach the Bond under which the etion of the involved operations nal Abandonment Notices shall be	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31	and true vertical depths of all pent reports shall be filed within 160-4 shall be filed once testing tor has determined that the site.	artinent markers and zone 30 days following compl g has been completed Fi is ready for final inspect	es Attach the Bond under which the etion of the involved operations nal Abandonment Notices shall be	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the opera Replaced bad tubing. Returned to production February 15	and true vertical depths of all pent reports shall be filed within 160-4 shall be filed once testing the filed once testing for the filed once testing for the filed once testing for the filed once th	and completed First search of the completed First ready for final inspect.	bs Attach the Bond under which the etion of the involved operations nal Abandonment Notices shall be ion.)  DFOR RECORD	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the operation Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF	and true vertical depths of all pent reports shall be filed with proceedings of the filed one testing too has determined that the site, 2010.	artinent markers and zone 30 days following compl g has been completed Fi is ready for final inspect	bs Attach the Bond under which the etion of the involved operations nal Abandonment Notices shall be ion.)  DFOR RECORD	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the opera Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF	and true vertical depths of all print reports shall be filed within 160-4 shall be filed once testing too has determined that the site, 2010.	and completed First ready for final inspect	bs Attach the Bond under which the etion of the involved operations and Abandonment Notices shall be ton.)  DFOR RECORD	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the operation Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF	and true vertical depths of all print reports shall be filed within 160-4 shall be filed once testing too has determined that the site, 2010.	and completed First ready for final inspect	as Attach the Bond under which the etion of the involved operations and Abandonment Notices shall be ion.)  DFOR RECORD  R 3 2010	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the opera Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF  RECENTAGE  APR 0 5 2  HOBBSC	and true vertical depths of all pent reports shall be filed within 160-4 shall be filed once testing too has determined that the site of the control of the	and completed First ready for final inspect	as Attach the Bond under which the etion of the involved operations and Abandonment Notices shall be ion.)  DFOR RECORD  R 3 2010	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the operation Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF  APR 0 0 2 APR 0 0 2 APR 0 0 2 APR 0 0 3 APR 0 0 3 APR 0 0 3 APR 0 3	Agent  Agent  Agent	and completed First ready for final inspect	as Attach the Bond under which the etion of the involved operations and Abandonment Notices shall be ion.)  DFOR RECORD  R 3 2010	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the operation Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF  APR 0 & 7  HOBBSC  14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Debbie McKelvey  Title  Signature  Date 3  THIS SPACE FOR FEDERAL OR S	Agent  Agent  Agent	and composition of the compositi	as Attach the Bond under which the etion of the involved operations and Abandonment Notices shall be ion.)  DFOR RECORD  R 3 2010	
to deepen directionally or recomplete horizontally, give subsurface locations and measured a work will be performed or provide the Bond No on file with BLM/BIA Required subseque If the operation results in a multiple completion or recompletion in a new interval, a Form 31 Filed only after all requirements, including reclamation, have been completed, and the opera Replaced bad tubing. Returned to production February 15 24-hr. test: 1 BO, 10 BW, 6 MCF  RECENTARY OBSECTION APR OBSECTION APR OBSECTION APR OBSECTION APR OBSECTION APR OBSECTION APR OBSECTION OF THE PROBLEM APR OBSECTION OF THE PROBLEM OF THE Signature Additional Correct Name (Printed/Typed) Debbie McKelvey  Title  Signature Additional April 1981	Agent  TATE OFFICE USE	and composition of the compositi	TAND MANAGEMENT  BAD FIELD OFFICE	