RECEIVED

DEC 14 2009

Form C-144 June 24, 2008

1625 N French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico District I State of New Mexico
1625 N French Dr., Hobbs, NM 88240 BSOGERergy Minerals and Natural Resources Department Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

For temporary pits, closed-loop systems, and below-grade tanks, submit to the appropriate NMOCD District Office. For permanent pits and exceptions submit to the Santa Fe Environmental Bureau office and provide a copyriothe misophie of the Santa Fe Environmental Bureau office and provide a copyriothe misophie of the santa Fe Environmental Bureau of the Santa Fe Environmental Bureau

	em, Below-Grade Tank, or IIII 17 7008
Proposed Alternative Method	Permit or Closure Plan Application DOC
	ystem, below-grade tank, or proposed alternative fields
Closure of a pit, closed-loop	system, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per is	dividual pit, closed-loop system, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of lie	ability should operations result in pollution of surface water, ground water or the
	ply with any other applicable governmental authority's rules, regulations or ordinances.
Operator: A mache Corporation	
Address: 10/20 5 Vale, Ste 1500	·
Facility or well name: New Mexico State	5 59
API Number: 30-025-37014	OCD Permit Number.
U/L or Qtr/Qtr O Section 2 Township 2:	Range 3/E County: Lea
	Longitude <u>/03, /32289° W</u> NAD: ☑1927 ☐ 1983
Surface Owner: Tederal State Private Tribal Trust or Indian	Allotment
Pit: Subsection F or G of 19.15.17.11 NMAC	Closed-Ioop System: Subsection H of 19.15.17.11 NMAC
Temporary Drilling Workover	☐ Drying Pad ☐ Tanks ☑ Haul-off Bins ☐ Other
Permanent Emergency Cavitation Steel Pit	☐ Lined ☐ Unlined
Lined Unlined	Liner type: ThicknessmilLLDPE HDPE PVC
Liner type. Thickness mil LLDPE HDPE PVC	Other
Other String-Reinforced	Seams: Welded Factory Other
Seams: Welded Factory Other	Volume:bblyd³
Volume:bbl Dimensions: Lx Wx Di	Dimensions: Lengthx Width
Below-grade tank: Subsection I of 19.15.17.11 NMAC	Fencing: Subsection D of 19.15.17.11 NMAC
Volumebbl	☐ Chain link, six feet in height, two strands of barbed wire at top
Type of fluid:	Four foot height, four strands of barbed wire evenly spaced between one and
Tank Construction material:	four feet
Secondary containment with leak detection	Netting: Subsection E of 19.15.17.11 NMAC
Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off	Screen Netting Other
☐ Visible sidewalls and liner	☐ Monthly inspections
☐ Visible sidewalls only	Signs: Subsection C of 19.15.17 11 NMAC
Other	12'x24', 2' lettering, providing Operator's name, site location, and
Liner type: Thicknessmil HDPE PVC	emergency telephone numbers
Other	Signed in compliance with 19.15.3.103 NMAC
Alternative Method:	Administrative Approvals and Exceptions:
Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration	Justifications and/or demonstrations of equivalency are required. Please refer to 19 15 17 NMAC for guidance.
of approval.	Please check a box if one or more of the following is requested, if not leave
	blank;
	Administrative approval(s): Requests must be submitted to the appropriate division district or the Santa Fe Environmental Bureau office for
	consideration of approval.

Environmental Bureau office for consideration of approval.

Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Applicant must attach justification for request. Please refer to 19.15.17.10 NMAC for guidance. Siting criteria does not apply to drying pads or above-grade tanks associated with a closed-loop system.	
Ground water is less than 50 feet below the bottom of the temporary pit, permanent pit, or below-grade tank. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to temporary, emergency, or cavitation pits and below-grade tanks) Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No ☐ NA
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. (Applies to permanent pits) Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	Yes No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 500 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	Yes No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes No
Within a 100-year floodplain. - FEMA map	Yes No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19 15.17.9 Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached. Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19 15.17. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC Previously Approved Design (attach copy of design) API Number:	locuments are
Closed-loop Systems Permit Application Attachment Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached. Geologic and Hydrogeologic Data (required for on-site closure) - based upon the requirements of Paragraph (3) of Subsection B of Siting Criteria Compliance Demonstrations (required for on-site closure) - based upon the appropriate requirements of 19.15.17.11 NMAC Design Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.16.	of 19.15.17.9
Previously Approved Design (attach copy of design) API Number:	
HUBBS (لارال

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the docu attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Cilmatological Factors Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Er	ments are O SO S
Proposed Closure: 19.15.17.13 NMAC Type: □ Dnlling □ Workover □ Emergency □ Cavitation □ Permanent Pit □ Below-grade Tank ☒ Closed-loop System □	Alternative
Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method (Exceptions must be submitted to the Santa Fe Environmental Bureau for cons	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable source material are provided below. Requests regarding changes to certain siting criteria may require administrative approval from the appropriate district office or may be considered an exception which must be submitted to the Santa Fe Environmental Bureau office for consideration of approval. Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17.10 NMAC for guidance.	
Ground water is less than 50 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 50 and 100 feet below the bottom of the buried waste NM Office of the State Engineer - iWATERS database search; USGS, Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a private, domestic fresh water well or spring that less than five households use for domestic or stock watering purposes, or within 1000 horizontal feet of any other fresh water well or spring, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. - Written confirmation or verification from the municipality; Written approval obtained from the municipality	Yes No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within the area overlying a subsurface mine. - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
Within an unstable area. - Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map	Yes No
Within a 100-year floodplain FEMA map	☐ Yes ☐ No

Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMA	(C) Instructions: Each of the following items must be attached to the
slower plan. Planse indicate by a check mark in the box, that the documents	are attachea.
Descend and Procedures - based upon the appropriate requirements of 1	9.15.17.13 NMAC
Confirmation Sampling Plan (if applicable) - based upon the appropriate	requirements of Subsection F of 19.15.17.13 NWAC
Disposal Facility Name and Permit Number (for liquids, drilling fluids at Soil Backfill and Cover Design Specifications - based upon the appropria	ate requirements of Subsection H of 19.15.17.13 NMAC
Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsect Re-vegetation Plan - based upon the appropriate requirements of Subsect	ion Lof 19.15.17.13 NMAC
Re-vegetation Plan - based upon the appropriate requirements of Subsect Site Reclamation Plan - based upon the appropriate requirements of Subs	section G of 19.15.17.13 NMAC
L Ditte Vecigination Light - pased about ato appropriate regardences	O 1. (10 15 17 12 D NIMAC) furtherstings. Plants indoutify the facility
Waste Removal Closure For Closed-loop Systems That Utilize Haul-off Bir	18 Univ: (19.15.17.15.D INIVIAC) Instructions: Please indentity the faculty
The attitude for the disposal of liquids drilling fluids and drill cuffings.	
Disposal Facility Name: Sundance Incorporated	Disposal Facility Permit Number: 7777-07-0005
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of	of the following items must be attached to the closure plan. Please indicate,
the short work in the how that the documents are attached.	
Cities Criteria Compliance Demonstrations - based upon the appropriate	requirements of 19.15.17.10 NMAC
Proof of Surface Owner Notice - based upon the appropriate requiremen	a appropriate requirements of 19 15 17 11 NMAC
Construction and Design of Burial Trench (if applicable) based upon the	e appropriate requirements of 15.15.1
Protocols and Procedures - based upon the appropriate requirements of I Confirmation Sampling Plan (if applicable) - based upon the appropriate	a requirements of Subsection F of 19.15.17.13 NMAC
I Die board upon the appropriate requirement	te of Subsection P Of 19.13.17.13 INMAS
Disposal Facility Name and Permit Number (for liquids, drilling fluids a	ind drift cuttings of the case off-site closure standards cannot be achieved,
Coll Cover Design - based upon the appropriate requirements of Subsect	ion H of 19.13.17.13 twice
Do constation Plan - based upon the appropriate requirements of Subsection	tion 1 of 19.15.17.15 NMAC
Site Reclamation Plan - based upon the appropriate requirements of Sub	section G of 19.15.17.13 NMAC
Operator Application Certification: I hereby certify that the information submitted with this application is true, ac	curate and complete to the best of my knowledge and belief.
I hereby certify that the information submitted with this application is true, ac	Curato and complete to the data of the first
Name (Print): Sam Hampton	Title: Drilling Engineer Date: 7/16/08
Number of the state of the stat	-116 los
Signature.	Date:
e-mail address: 5@m hampton @afachecorp. Com	Telephone: 418-491-4954
C-man address5477_71077327	
OCD Approval: Permit Application (including closure plan) Closur	re Plan (only)
OCD Approval: Permit Application (including closure plan) Closure	
	Approval Date: 7/18/88
OCD Approval: Permit Application (including closure plan) Closur OCD Representative Signature:	Approval Date: 7/18/88
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title:	OCD Permit Number: P1-DD178
OCD Approval: Permit Application (including closure plan) Closur OCD Representative Signature:	OCD Permit Number: PI-DD 178
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect	OCD Permit Number: P1-DD178
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsection	OCD Permit Number: PI-DD178 tion K of 19 15.17.13 NMAC Closure Completion Date: 13 - 10-09
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method	OCD Permit Number: PI-DD178 tion K of 19 15.17.13 NMAC Closure Completion Date: 13 - 10-09
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain.	OCD Permit Number: 7/18/88 OCD Permit Number: 91-00178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12-10-09 ternative Closure Method
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method All If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following	OCD Permit Number: PI-DD178 tion K of 19.15.17.13 NMAC Closure Completion Date: 13.10.09
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method All If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached.	OCD Permit Number: 7/18/18 OCD Permit Number: 91-00178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12-10-09 ternative Closure Method
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method Ali If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice	OCD Permit Number: 7/18/88 OCD Permit Number: 91-00178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12-10-09 ternative Closure Method
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable)	Approval Date: 7/18/8 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method Ali If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Closure Notice Proof of Decd Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results	OCD Permit Number: 7/18/88 OCD Permit Number: 91-00178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12-10-09 ternative Closure Method
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method Ale If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results	Approval Date: 7/18/8 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Unisposal Facility Name and Permit Number	Approval Date: 7/18/8 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation	Approval Date: 7/18/8 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique	Approval Date: 7/18/8 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation)	Approval Date: 7/18/88 OCD Permit Number: PI - DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check IIII 17 2008
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method Ale If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude	Approval Date: 7/18/88 OCD Permit Number: PI-DD 178 tion K of 19 15.17.13 NMAC Closure Completion Date: 13 - 10 - 09 ternative Closure Method ing items must be attached to the closure report. Elicase indicate, by a check
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Certification:	Approval Date: 7/18/88 OCD Permit Number: PI-DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Pilease indicate, by a check IIII 17 2008 Ongitude NAD: 1927 1983
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method Ali If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Certification: I bereby certify that the information and attachments submitted with this closure Location:	Approval Date: 7/18/88 OCD Permit Number: PI - DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check IIII 17 2008 ongitude NAD: 1927 1983 sure report is true, accurate and complete to the best of my knowledge and
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Certification:	Approval Date: 7/18/88 OCD Permit Number: PI - DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12.10.09 ternative Closure Method ing items must be attached to the closure report. Filease indicate, by a check IIII 17 2008 ongitude NAD: 1927 1983 sure report is true, accurate and complete to the best of my knowledge and
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Waste Material Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Degrator Closure Certification:	Approval Date: 7/18/88 OCD Permit Number: PI - DD 178 tion K of 19.15.17.13 NMAC Closure Completion Date: 12 - 10 - 09 ternative Closure Method Items must be attached to the closure report. Fileass indicate, by a check IIII 1 7 2008 Ongitude NAD: 1927 1983 Sure report is true, accurate and complete to the best of my knowledge and
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure required.	Approval Date: 7/18/18 OCD Permit Number: PI - DD 178 tion K of 19 15.17.13 NMAC Closure Completion Date: 12 - 10 - 09 ternative Closure Method and items must be attached to the closure report. Filease indicate, by a check IIII 1 7 2008 Ongitude NAD: 1927 1983 Soure report is true, accurate and complete to the best of my knowledge and uirements and conditions specified in the approved closure plan.
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan Confirmation Sampling Analytical Results Disposal Facility Name and Permit Number Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude Operator Closure Certification: I hereby certify that the information and attachments submitted with this closure belief. I also certify that the closure complies with all applicable closure required.	Approval Date: 7/18/18 OCD Permit Number: PI - DD 178 tion K of 19 15.17.13 NMAC Closure Completion Date: 12 - 10 - 09 ternative Closure Method and items must be attached to the closure report. Filease indicate, by a check IIII 1 7 2008 Ongitude NAD: 1927 1983 Soure report is true, accurate and complete to the best of my knowledge and uirements and conditions specified in the approved closure plan.
OCD Approval: Permit Application (including closure plan) Closure OCD Representative Signature: Title: Closure Report (required within 60 days of closure completion): Subsect Closure Method: Waste Excavation and Removal On-Site Closure Method All If different from approved plan, please explain. Closure Report Attachment Checklist: Instructions: Each of the following mark in the box, that the documents are attached. Proof of Closure Notice Proof of Deed Notice (if applicable) Plot Plan On-Site Closure Results Sampling Analytical Results Soil Backfilling and Cover Installation Re-vegetation Application Rates and Seeding Technique Site Reclamation (Photo Documentation) On-site Closure Location: Latitude	Approval Date: 7/18/18 OCD Permit Number: PI-DD 178 tion K of 19 15.17.13 NMAC Closure Completion Date: 12 - 10 - 09 ternative Closure Method and items must be attached to the closure report. Fileass indicate, by a check IIII 1 7 2008 Ongitude NAD: 1927 1983 Source report is true, accurate and complete to the best of my knowledge and differents and conditions specified in the approved closure plan. Title: Duling Engineer

4-13/1/ Option Division

APACHE CORPORATION <u>CLOSED-LOOP SYTEM DESIGN, OPERATION, MAINTENANCE AND CLOSURE</u> PLAN – revised 7/16/2008

TYPICAL FOR NEW MEXICO WELLS

This document is intended to provide design requirements as well as operating, maintenance and closure instructions for closed-loop (drilling fluid) systems, ensuring compliance with the New Mexico Title 19, Chapter 15, Part 17 rules and regulations. Drilling units operating for Apache Corporation in New Mexico should be rigged up with a closed-loop system consistent with this design and should be operated, maintained and closed in a manner consistent with this document.

Design

The closed-loop system shall be designed and construct to ensure the confinement of oil, gas or water and to prevent uncontrolled releases. We will utilize cuttings bins to contain drilled solids for transport and disposal off site at a New Mexico licensed disposal facility. Figure 1. – New Mexico Typical Closed Loop System is attached for reference when reviewing the following design specifications.

The minimum solids removal equipment shall include a high speed shaker and a centrifuge.

- The shale shaker(s) shall be placed to receive all of the fluid and cuttings as they return from the well bore. Entry from the flow line shall be such that splash is minimized. It shall be placed such that the drilled solids that are removed by the screen are easily conveyed to the cuttings bin(s). If a slide is required it should be designed with as much slope as possible to minimize maintenance while drilling.
- The centrifuge shall be fed by a dedicated centrifugal pump from the first active mud tank. It shall be placed such that the drilled solids removed dump directly into the cuttings bin(s). The liquid recovered should be gravity returned to the active mud system, down stream of the feed pump suction.

The minimum active mud system volume shall be 500 barrels. Tank(s) shall be of steel construction and in a condition such that no leaks or uncontrolled releases would be expected.

- The tanks shall be equipped with a jetting system to allow emptying of the tanks into an above ground container.
- Any dump valves shall be in good condition and left closed at all times during regular drilling operations.
- Tank bottoms shall be sloped to facilitate clean out.





In addition to the active mud tank(s) the closed-loop system shall include at a minimum two additional steel tanks for fluid containment. Both tanks shall be placed such that fluid can easily be drawn out of them on an as needed basis with vacuum trucks.

- One steel tank shall be placed such that it can receive fluid from the choke
 manifold. This same tank shall be placed where returns from the well bore during
 cementing operations can be directed into it, diverting cement returns from the
 active mud system.
- Another steel tank shall be placed such that the active mud system can be jetted into it when dilution is required.

All drilled solids removed from the well bore and recovered from the drilling fluid shall be collected in steel "haul-off" bins. These temporary pits for solids management shall comply with any <u>applicable</u> requirements for temporary pits specified in 19.15.17 NMAC.

- Cuttings bins shall be of steel construction and be capable of being closed during transport to prevent spillage.
- Cuttings bins shall be constructed and placed in a manner to facilitate removal of full bins and placement of empty bins with out disrupting the drilling operations.

The entire closed-loop system as described above, with the exception of the active mud tanks, shall be placed on a 20 mil nylon reinforced liner for splash containment.

- The liner shall be of size and installed in a manner that splash from normal operations such as fluid transfer, jetting of tanks, washing down of shaker slide, etc of the closed-loop system does not reach the soil on the location.
- The liner shall be installed in a manner such that run on of surface water does not occur, and run off of splash fluids does not occur.

Operation and Maintenance

The closed-loop system shall be operated and maintained at all times in such a manner as to prevent contamination of fresh water and protect the public health and the environment. While Apache Corp relies on various third party vendors to provide, operate and maintain the closed-loop system, in the end it is the Apache Corp on-site representative who must take responsibility for the effective operation of the system. At the end of the well, all drilling fluids and drilled solids should be disposed of in a licensed disposal facility in New Mexico.

Know which licensed and approved disposal facility is closest to your location and verify they are capable and prepared to receive the cuttings and fluids from your well. Track all loads sent during the drilling of the well and up to the time the rig is moved off of the location.



Current approved facilities are;

- Controlled Recovery Inc. (877) 505-4274
- Sundance Incorporated (575) 394-2511

Ensure that the closed-loop system meets the design criteria listed above and is properly installed and fully functional prior to spud.

The shale shaker(s) must be run at all times while drilling unless the use of lost circulation material (LCM) prevents it. The shaker(s) should also be run as required while tripping to ensure that any displacement from the well bore is returned to the active system and does not run over the (stopped) shale shaker screens.

- The finest mesh screens that will not cause excessive fluid discharge shall be used at all times. Torn screens should be replaced as soon as possible.
- The shale slide shall be inspected regularly through out a tour and kept clean such that drilled solids do not build up and spill over the sides, missing the cuttings bins.

The centrifuge should be run at all times while drilling fluid is maintained in the active mud system. Continual use will reduce dilution requirements.

- The centrifuge and associated feed pump should be checked regularly through out a tour to ensure they are running properly. Call for a service man as soon as possible if they are found not to be working properly or at all.
- Check for and correct immediately any leaks in the feed pump suction and discharge lines.

Inspect the active system tanks at least every tour to ensure no drilling fluid is leaking onto the location. Check any dump valves and interconnecting pipes for leaks. Correct any leaks as soon as possible upon detection.

• Jet active mud system as required to maintain desired mud weight. Be sure the jetting lines are secure and do not cause excessive splash at the steel holding tank.

Monitor and know/plan the fluid level in the steel fluid containment pits. Call for vacuum trucks with enough lead time to allow for possible delays.

- Plan for displaced fluid during cement jobs. Ensure enough vacuum trucks are on hand as required before beginning your cementing job.
- Do not mix fresh water and brine water if possible. Completely empty fresh water from the steel tanks before converting the mud system to brine water.





Page 3 of 5

Inspect cuttings bins at least once per tour, noting their level, any spills and any damage to the containers that could result in loss of cutting containment.

- Ensure that you have enough empty volume to handle the high rates of penetration expected on surface holes and other portions of the wells.
- Ensure cuttings bin tops are closed before leaving location en route to the disposal site.

Check the condition of the splash containment liner daily. Look for any leaks and splash accumulation that needs to be cleaned up. Repair any leaks in the liner immediately.

• Clean up any splash accumulation on the liner using diaphragm pumps, vacuum trucks and other means as necessary.

Make every effort to operate and maintain the closed-loop system in a manner that puts no drilling fluid or well bore discharge/cuttings in contact with the location or surrounding area.

In the event of an oil spill that reaches water, or an oil spill to land over five (5) barrels take immediate action to contain the spill and make to following notifications;

- EHS Apache Hotline; 800 874-3262
- NMOCD

In the event of oil reaching water include the following notification;

• Environmental Protection Agency (EPA) National Response Center

Closure

The "closure" of the closed-loop system must be completed within six months of the date the drilling rig is released from the location. A Closure Report must be filed with the New Mexico Oil Conservation Division within 60 days of completing the closure.

"Closure" of a closed-loop system begins with the proper disposal of all liquid mud and cuttings that are on location upon rig release. The cuttings and liquid should be transported to an approved disposal facility. This includes any fluid or solids that may be on the surface of the splash containment liner. See operating instructions above.

Next all of the equipment associated with the closed-loop system must be removed. This includes steel tanks, cuttings bins and rails. Ensure that equipment being removed and transported to the next location or other facility is clean and in such a state that no waste will be discharged during transportation.

Once all of the equipment has been removed the splash containment liner material must be gathered up and disposed of in an approved disposal facility. Ensure the liner is recovered in such a manner that any contamination is "folded in" and no discharge will



Page 4 of 5



occur during transportation to the disposal facility. Visually search for any wet areas, discoloration or other evidence of a mud or cuttings release to the surface. If there is no evidence of any release proceed with filing the closure report.

If there is evidence of a release of mud or cuttings to the surface collect individual grab samples from the potentially contaminated area and analyze for benzene, total BTEX, THP, the GRO and DRO combined fraction and chlorides to demonstrate that benzene, as determined by EPA SW-846 method 8021B or 8260B or other EPA method that the division approves, does not exceed 0.2 mg/kg; total BTEX, as determined by EPA SW-846 method 8021B or 8260B or other EPA methods that the division approves, does not exceed 50 mg/kg; TPH, as determined by EPA SW-846 method 418.1 or other EPA method that the division approves does not exceed 2500 mg/kg; the GRO and DRO combined fraction determined by EPA SW-846 method 8015M, does not exceed 500 mg/kg; and chlorides as determined by EPA method 300.1 do not exceed 500 mg/kg or the background concentration, whichever is greater.

When closure is completed a closure report must be filed with the NMOCD within 60 days. The filing consists of printing a copy of the C-144 that was approved previously, completing the Closure Report on page 4 and submitting it to the NMOCD.

For our closed-loop systems in the <u>Closure Report</u> area of the form we will provide the closure completion date and check the "Closure Completion Date" box found approx. 2/3 of the way down the page. In the <u>Closure Method</u> area, check the "Waste Excavation and Removal" box. In the <u>Closure Report Attachment Checklist</u> put a check mark in the "Disposal Facilities Name and Permit Number". In the space to the right of the checklist write in the name(s) of the disposal facility or facilities used during both the drilling and the closure phase of the closed-loop operation. If there was no evidence of liner leakage of splashed mud or cuttings then complete the <u>Operator Closure Certification</u> box at the bottom of page 4 of Form C-144, sign and date it and submit it to the NMOCD.

If there was evidence of liner leakage requiring samples and analysis, in addition to the instructions for completing Form C-144 listed above, check the "Confirmation Sampling Analytical Results" box in the <u>Closure Report Attachment Checklist</u> and attach a copy of the soil analysis report.

Prepared by

July 2, 2008

Sam Hampton, P.E. Drilling Engineer

Attachment:

Figure 1. – New Mexico Typical-Closed-Loop System

HOBBS OCD

Page 5 of 5

