Submit 3 Copies To Appropriate District St	ate of New Mexico	Form C-103
Office Energy Minerals and Natural Resources		June 19, 2008 WELL API NO.
District I 1625 N. French Dr., Hobbs, NM183340 District II 1301 W. Grand Ave. Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aziec, NM 87409 111 2014 Conto For NIM 87505		30-025-06392
1301 W. Grand Ave . Artesia. NM 88210 PONSERVATION DIVISION		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aziec, NM 87419 10 2010 Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District W Salita PC, NW 67505		6. State Off & Gas Least 140.
1220 S. St. Francis Dr., Santa HONDON CO. 87505		7. Lease Name or Unit Agreement Name
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Least Name of Olite Agreement value
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		E. C. Hill A
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 1
2. Name of Operator		9. OGRID Number 012024
John H. Hendrix Corporation		10. Pool name or Wildcat
3. Address of Operator P. O. Box 3040, Midland, TX 79702-3040		Blinebry Oil & Gas
4. Well Location		
Unit Letter K : 3330 feet from the North line and 1980 feet from the West line		
Section 4 Township 21S Range 37E NMPM Lea County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3443' GL		
Detail of the College Details of the College		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLANS		
PULL OR ALTER CASING		
DOWNHOLE COMMINGLE		
OTHER: OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.		
Suspect casing leak 2500-3500'. 1. Test csg to locate leak area.		
2. Sqz leak area, WOC.		
3. Drill out cmt, test sqz.		
4. Return to production.		
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Cherly Dro Kg	TITLE Engineer	DATE 5/10/10
Type or print name . Carolyn Doran Haynes . E-mail address: cdoranhaynes@jhhc.org PHONE: 432-684-6631		
APPROVED BY: TITLE TITLE DATE DATE		
APPROVED BY:		