

Submit 1 Copy To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
October 13, 2009

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other SWD	7. Lease Name or Unit Agreement Name MONUMENT DISPOSAL (35738)
2. Name of Operator MONUMNET DISPOSAL INC	8. Well Number #1
3. Address of Operator 1314 BRITTANY, HOBBS, NM 88240	9. OGRID Number 242044
4. Well Location Unit Letter <u>H</u> : <u>2582</u> feet from the <u>N</u> line and <u>809</u> feet from the <u>E</u> line Section <u>35</u> Township <u>19S</u> Range <u>36E</u> NMPM LEA County	10. Pool name or Wildcat SWD; SAN ANDRES
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: ☒

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. Notify OCD Hobbs office at least 24 hours prior to working on well
2. Pull tubing and packer.
3. RIH with work string, set bridge plug appx 4260
4. Pressure test well to 500 PSI.
5. Retrieve bridge plug
6. RIH with packer, interval coated tubing
7. Pressure test well with chart
 - A. If well test successful submit follow up C103 with chart to OCD.
 - B. If test unsuccessful follow up C103 to OCD with plan of action to repair well.

RECEIVED

MAY 07 2010

HOBBSOCD

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

[Signature]

TITLE

VP

DATE

5-7-10

Type or print name

E-mail address:

PHONE:

For State Use Only

APPROVED BY:

[Signature]

TITLE

OCD DISTRICT SUPERVISOR/GENERAL MANAGER

DATE

MAY 07 2010

Conditions of Approval (if any):