Form 3160-5 (April 2004)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

CD-HOBBSRECEIV APR 2 8 2 15. Lease Serial No.

OM B No 1004-013

	,	-	Ρ,
SUNDRY NOTICES AND REPORTS ON WELLS	. I'm		ł
SOURCES AND REPORTS ON METER	HH C.		l
not use this form for property to the		11	t
, not use tills lottil for proposals to drill or to re-enter s	n [⊤] `	-	۱×

LC 032650B

Do olf Indian, Allottee or Tribe Name abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit or CA/Agreement, Name and/or No. A)TE- Other instructions on reverse side. I. Type of We Other 8. Well Name and No. 2. Name of Operator A.B. Coates "C" Federal #22 Chevron USA Inc API Well No. 3a. Address 3b Phone No (include area code) 30-025-11744 15 Smith Rd., Midland, TX 79705 432-561-8600 10 Field and Pool, or Exploratory Area 4 Location of Well (Footage, Sec., T., R, M, or Survey Description) MID JUSTIS ABO GAS/JUSTIS; MO 11. County or Parish, State UL B, Sec. 24-T25S-R37E 660' FNL & 2310' FEL Lea, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Acidize Production (Start/Resume) Deepen Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Casing Repair Subsequent Report New Construction Recomplete Change Plans Plug and Abandon Temporarily Abandon __ Final Abandonment Notice Convert to Injection Plug Back Water Disposal Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones.

- Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection)
 - 1. Notify BLM 24 hrs prior to MI and RU.
 - 2. RIH set TAG CIBP at 5150', spot 40sx, plug from 5150'-4950'.
 - 3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL.
 - 4. Spot 40sx of cement from 3400'-3200' (shoe).
 - 5. Perf 4 holes at 2100', sqz 70sx, plug from 2100'-1900' (B-Salt) WOC Tag.
 - 6. Perf 4 holes at 1350', sqz 65sx, plug from 1350'-1150' (T-Salt) WOC Tag.
 - 7. Perf 4 holes at 633', sqz 90sx, plug from 633'-350' (Shoe/Fr. Wtr.) WOC Tag.
 - Perf 4 holes at 60', sqz 30sx, plug from 60'-surface (surface) WOC Tag.
 - 9. Install dry hole marker.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

RECLAMATION PROCEDURE ATTACHED

 I hereby certify that the foregoing is true and correct Name (Printed/Typed) 	<u> </u>						
M. Lee Roark	Title Agent for Chevron USA, inc.						
Signature M. La Konh	Date			04/22/2010			
THIS SPACE FOR FEDERAL	9R S	TATE	OFF	ICAHSER(OVED		
Approved by Approved by Approved by	0/10	itle			Date		
Conditions of approval, if any are attached Approval of this notice does not warrar certify that the applicant boids legal or equitable title to those rights in the subject lead which would entitle the applicant to conduct operations thereon	ntor	Office		APR 2 s/ Dustin	6 2010 Winkler	£ -3,	
Title 18 USC Section 1001 and Title 43 USC Section 1212, make it a crime for any States any false, fictitious or fraudulent statements or representations as to any matter	person ki r within it	nowingly s jurisdic	and 🚱	UREAU (OFLIANT CARLSBAD FI	MANAGEME ELD OFFICE	gency	of the United

