Submit 1 Copy To Appropriate District	State of New Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88240 District II	nergy, Minerals and Natural Resources	October 13, 2009
1625·N. French Dr., Hobbs, NM 88240	VEN	WELL API NO.
District II	MI CONSEDUATION DIVISION	30-025-34495
1301 W. Grand Ave, Artesia, NM 8821127		5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 8740BBSO	Viol 220 South St. Francis Dr.	STATE S FEE S
District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505		
	ND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION F		South Shoebar 15 State V
PROPOSALS.)	CR PERMIT (FORM C-101) FOR SUCH	
1. Type of Well: Oil Well Gas We	ell 🛛 Other SWD 🗸	8. Well Number 1
2. Name of Operator		9. OGRID Number 6137
Devon Energy Production Company, LP		y. Colab Ivamor
3. Address of Operator		10. Pool name or Wildcat
20 North Broadway, Oklahoma City, Oklah	noma 73102	Midway; Upper Penn, West
		,,
4. Well Location		
Unit LetterG:1980_fe	et from theNorth line and1850	feet from theEast line
Section 15	Township 17S Range 35E	NMPM County Lea
	evation (Show whether DR, RKB, RT, GR,	etc.)
A April 1995 The Control of the Cont	3950'	
		The second secon
10 (1 1 4	' D A I I' A NI A CNI A	D Odl D
12. Check Approp	riate Box to Indicate Nature of Not	ice, Report or Other Data
NOTICE OF INTENT	ION TO	LIDOEOLIENT DEDODT OF
NOTICE OF INTENT	· · · · · · · · · · · · · · · · · · ·	SUBSEQUENT REPORT OF:
	AND ABANDON REMEDIAL V	_
TEMPORARILY ABANDON _ CHAN	IGE PLANS □ COMMENCE	DRILLING OPNS.□ P AND A □
· 		<u> </u>
· 	IPLE COMPL CASING/CE	MENT JOB
· 		MENT JOB
PULL OR ALTER CASING MULT	IPLE COMPL CASING/CEN	MENT JOB BUT
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER:	IPLE COMPL CASING/CEN	Pressure Test ⊠
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op-	CASING/CEN OTHER: erations. (Clearly state all pertinent detail	Pressure Test s, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op-	CASING/CEN OTHER: erations. (Clearly state all pertinent detail	Pressure Test ⊠
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op-	CASING/CENT OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple	Pressure Test s, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op of starting any proposed work). SE	CASING/CENT OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple	Pressure Test s, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op of starting any proposed work). SE	CASING/CENT OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple	Pressure Test s, and give pertinent dates, including estimated date
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op of starting any proposed work). SE	CASING/CEN OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on.	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion	CASING/CEN OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on.	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for	Pressure Test s, and give pertinent dates, including estimated date c Completions: Attach wellbore diagram of ollows:
PULL OR ALTER CASING	TIPLE COMPL OTHER: Casing/CEN OTHER: Perations. (Clearly state all pertinent detail pert	Pressure Test Is, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of ollows: pressure – well pasted test.
PULL OR ALTER CASING	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for the messed by OCD. Open surface valve – no	Pressure Test Is, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of ollows: pressure – well pasted test.
PULL OR ALTER CASING	TIPLE COMPL OTHER: Casing/CEN OTHER: Perations. (Clearly state all pertinent detail pert	Pressure Test Is, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of ollows: pressure – well pasted test.
PULL OR ALTER CASING	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for the messed by OCD. Open surface valve – no	Pressure Test Is, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of ollows: pressure – well pasted test.
PULL OR ALTER CASING	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for messed by OCD. Open surface valve – no Rig Release Date: 8/10/99	Pressure Test s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for messed by OCD. Open surface valve – no Rig Release Date: 8/10/99	Pressure Test s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING	OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. erformed a pressure test on 8-04-2009 as for messed by OCD. Open surface valve – no Rig Release Date: 8/10/99	Pressure Test s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING MULT DOWNHOLE COMMINGLE MULT OTHER: 13. Describe proposed or completed op of starting any proposed work). SE proposed completion or recompletion Devon Energy Production Company, L.P. per 8-04-2009 MIT-test, no truck required. With Spud Date: 9/14/98 I hereby certify that the information above is	TIPLE COMPL OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing of the second o	s, and give pertinent dates, including estimated date completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING	TIPLE COMPL OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing/CEN OTHER: Casing of the second o	Pressure Test s, and give pertinent dates, including estimated date e Completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING	TITLE_Fr. Staff Engineering	Pressure Test So, and give pertinent dates, including estimated date expected to the completions: Attach wellbore diagram of collows: pressure — well pasted test. TechnicianDATEMay 6, 2010
PULL OR ALTER CASING	TITLE_Fr. Staff Engineering	s, and give pertinent dates, including estimated date completions: Attach wellbore diagram of collows: pressure – well pasted test.
PULL OR ALTER CASING	TITLE_Fr. Staff Engineering	Pressure Test So, and give pertinent dates, including estimated date expected to the completions: Attach wellbore diagram of collows: pressure — well pasted test. TechnicianDATEMay 6, 2010
PULL OR ALTER CASING	CASING/CEN OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. Orformed a pressure test on 8-04-2009 as for nessed by OCD. Open surface valve – no Rig Release Date: 8/10/99 true and complete to the best of my know TITLE_Fr. Staff Engineering E-mail address: _norvella.adams@	Pressure Test So, and give pertinent dates, including estimated date expected to the completions: Attach wellbore diagram of collows: pressure — well pasted test. Pledge and belief. TechnicianDATEMay 6, 2010 dvn.com _ PHONE: _(405) 552-8198
PULL OR ALTER CASING	TITLE_Fr. Staff Engineering	Pressure Test So, and give pertinent dates, including estimated date of Completions: Attach wellbore diagram of collows: pressure – well pasted test. Pressure – well pasted test. Pressure – well pasted test. TechnicianDATEMay 6, 2010 dvn.com _ PHONE: _(405) 552-8198
PULL OR ALTER CASING	CASING/CEN OTHER: erations. (Clearly state all pertinent detail E RULE 19.15.7.14 NMAC. For Multiple on. Orformed a pressure test on 8-04-2009 as for nessed by OCD. Open surface valve – no Rig Release Date: 8/10/99 true and complete to the best of my know TITLE_Fr. Staff Engineering E-mail address: _norvella.adams@	Pressure Test So, and give pertinent dates, including estimated date expected to the completions: Attach wellbore diagram of collows: pressure — well pasted test. Pledge and belief. TechnicianDATEMay 6, 2010 dvn.com _ PHONE: _(405) 552-8198