Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103 October 13, 2009
District I	Energy, Minerals and Natural Resources	
District II	CONSERVATION DIVISION	30-025-39570
1301 W Grand Ave, Artesia, NM 88210	単純 CONSERVATION DIVISION	5. Indicate Type of Lease
District III 1000 Rio Brazos Rd , Aztec, NM 87416 4 2	1220 South St. Francis Dr.	STATE S FEE
D IV	Dallia EV. INIVEO 1.303	6. State Oil & Gas Lease No.
1220 S St Francis Dr , Santa Full DOSU	CD	
87505	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	LS AND REPORTS ON WELLS LS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Hulkster
DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		8. Well Number 3
PROPOSALS)		8. Well Number 3
1. Type of Well: Oil Well Gas Well Other		9. OGRID Number 6137
Name of Operator Devon Energy Production Company, LP		9. OGRID Number 0137
3. Address of Operator		10. Pool name or Wildcat
20 North Broadway, Oklahoma City, Oklahoma 73102		Lusk; Bone Spring, North
4. Well Location		
Unit Letter B: 660 feet from theNorth line and1980feet from theEast line		
Section 32 18S Township 32E Range NMPM County Lea 11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3704' GR		
3701 GK		
12 Check An	propriate Boy to Indicate Nature of Not	ice Report or Other Data
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT O		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR		-
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A		DRILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB		
DOWNHOLE COMMINGLE		
	· □ OTUED	D
OTHER:		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of		
proposed completion or recompletion.		
3/23/2010 MIRU.		
3/24/2010 Tag DV tool at 5909' and test casing and BOP rams to 1500 psi – good. Drill DV tool and circulate hole clean. RIH with		
tubing and tag PBTD at 9527'. Test casing to 1500 psi – good. POOH with tubing.		
3/25/2010 ND BOP and NU frac valve.		
3/26/2010 RIH and perforate Bone Springs from 9179'-9359' with 2 spf; 36 holes.		
3/29/2010 Spearhead with 3000 gallons 7.5% NEFE. Frac with 80,000 gallons Spectra Star 2500, 103,001 # 20/40 White sand and 37,662# 16/30 Siber Prop. RIH with CBP and set CBP at 8,900'. Test to 1500 psi – ok. Perforate 1st Bone Spring from 8344'- to 8409'		
with 2 spf, 28 holes. Spearhead with 2000 gallons 7.5% NEFE. Acid frac with 44,500 gallons Spectra Star 2500, 61,671 # 20/40 White		
sand, and 19,890 # 16/30 Siber Prop.		
3/30/2010 ND frac valve and NU BOP. RIH and tag sand at 8890'. Wash sand and drill CBP at 8900'. Circulate hole clean. RIH and		
wash sand to PBTD at 9527'. Circulate hole clean. POOH with tubing.		
3/31/2010 RIH with production tubing. ND BOP and NU wellhead.		
4/01/2010 RIH with pump and rods.		
4/05/2010 RDMO. 4/06/2010 Hook up wellhead and flowline.		
4/08/2010 Pump test to battery.	inic.	
,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		
Spud Date: 2/19/2010	Rig Release Date: 4/5/20	10
2/19/2010	17.57.20	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Fr. Staff Engineering Technician DATE 3/22/10		
SIGNATURE Fr. Staff Engineering Technician_DATE3/22/10_		
Type or print name Norvella Adams E-mail address: _norvella.adams@dvn.com PHONE: _(405) 552-8198		
For State Use Only		
	PETROLEUM E	Water JUN 9 2 2010
APPROVED BY:		
Conditions of Approval (if any):		