

From: 5756270276

Page: 2/3

Date: 6/2/2010 5:23:04 PM

JUN-06-10

04:14PM

FROM-UNITED STATES DEPT OF INTERIOR BLM RUS

010 001 0010

1040 P.002/003 F-851

OPERATOR'S COPY

Form 3160-5
(August 2007)UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENTSUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

EnerVest Operating, L.L.C.

3a. Address

1001 Fannin, Suite 800
Houston, TX 77002

3b. Phone No. (include area code)

713-495-6537

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

34 25 31E
300 ft. Two 205 - Reg 3PE
680 FSL and 680 FSL (Unit)
530 ENL & 440 FSL

3. Lease Serial No.

NMNMOB153A

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.

Western Reserves 34 Federal #

9. API Well No.

30-005-20760

10. Field and Pool or Exploratory Area

Tom Tom-San Andres

11. Country or Parish, State

Chaves County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☒ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleting horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

4-8-10: BLM contacted to witness MIT. Kevin Bussell gave go ahead without witness.

4-9-10: Successful MIT performed.
Please see attached chart.
Top perf = 3877'. CIBP = 3777'.

EnerVest Operating, L.L.C. respectfully requests Temporary Abandonment approval due to the following justifications:

1. We request that this well be TA now in order to remove it from the NMOCs Inactive Well List. Due to the number of wells currently on this list, we are utilizing all of our efforts to bring every inactive well in NM into compliance and keep them off of this list.
2. After further evaluation, if the well is not deemed economical, plans to P&A will be submitted by 5-13-2011.

TA APPROVED FOR 6 MONTH PERIOD
ENDING OCT 09 2010

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Bridget Helfrich

Title Regulatory Tech.

Signature

Bridget Helfrich

Date 05/13/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

David R. Glass EG6-7-10

PETROLEUM ENGINEER

Date

JUN 01 2010

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would enable the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Continued on page 2)

P.M.

