RECEIVED

Submit 3 Copies To Appropriate District State of New Me	xico Form C-103
Office HORHS (#162). Minerals and Natur	ral Resources March 4, 2004
1625 N French Dr , Hobbs, NM 88240	WELL API NO. 20_055053
1301 W Grand Ave, Artesia, NM 88210 District III OIL CONSERVATION 1220 South St. Fran	5. Indicate Type of Lease
1000 Rio Brazos Rd, Aztec, NM 87410	STATE L TEE V
District IV 1220 S St Francis Dr, Santa Fe, NM 87505	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLU DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FO PROPOSALS)	G.C. Matthews ✓
1. Type of Well:	8. Well Number
Oil Well ☐ Gas Well ☑ Other ✓	12 /
2. Name of Operator Chevron USA, Inc.	9. OGRID/Number / 4323
3. Address of Operator	10. Pool name or Wildcat
#15 Smith Rd., Midland, Tx 79705	Monument Tubb; West
4. Well Location	
Unit Letter P : 330 feet from the South	line and 990 feet from the East line
	nge 37-E NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: UL P Sect 6 Twp 20S Rng 37E Pit type Steel Depth to Groundwater Distance from nearest fresh water well Over 1000	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng; 330 feet from the South line and 990 feet from the East_line	
1000 feet from the 1000 feet fro	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK D PLUG AND ABANDON D	SUBSEQUENT REPORT OF: REMEDIAL WORK ALTERING CASING
-	
TEMPORARILY ABANDON	COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	CASING TEST AND CEMENT JOB
OTHER:	OTHER.
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multipl or recompletion.	e Completions: Attach wellbore diagram of proposed completion
1 Notified OCD 24 hrs prior to MIRU to P & A 5-20-10 10 Pe 2 Spot 100sx Cmt@3510'. 5-27-10 Tag@3380' 5-28-10 11. Ins	erf@60' Unable to EPIR Spot 50sx Cmt Plug F/140' to Surf 6-7-10 stall Dry Hole Marker & Clean Location 6-8-10
3 Spot 100sx Cnt@3347' 5-28-10 Tag@2047' 6-1-10 4 /Perf & SQZ 150sx Cnt@2000' 6-1-10 Tag@1527' 6-2-10 5 /Perf & SQZ 60sx Cnt@1180' 6-2-10 Tag@910' 6-3-10	Approved for plugging of well bore only. Liability under bond is retained pending receipt
6 Perf & SQZ 115sx Cml@500' 6-3-10 No Tag 7 ReSQZ 100sx Cml@500' 6-3-10 No Tag	of C:103 (Subsequent Report of Well Plugging)
8 ReSQZ 100sx Cmt@500'. 6-4-10 No Tag 9 ReSQZ 100sx Cmt@500' 6-4-10 Tag@140'. 6-7-10	which may be found at OCD Web Page under Firms, www.emard.stare.nm.us/ocd.
I hereby certify that the information above is true and complete to the be	est of my knowledge and belief. I further certify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidelines	
SIGNATURETITLE	MANA 66A DATE 6-8-10
Type or print name Jimmy BA6CEY E-mail address: sunsetwellservice@yahoo com Telephone No. 432-561-8600	
(This space for State use)	
APPPROVED BY TITLE	DATE DATE 16-10
	DATIO-16-10
Conditions of approval, if any.	·