



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Response Required – Deadline Enclosed

Field Inspection Program

"Preserving the Integrity of Our Environment"

17-Jun-10

JAY MANAGEMENT COMPANY, LLC

2425 WEST LOOP SOUTH STE 810

HOUSTON TX 77027

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.


INSPECTION DETAIL SECTION

COLLIER No.001				F-9-11S-33E	30-025-00994-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
06/15/2010	Plugged Well Surface Restor	Maxey Brown	Yes	No	9/18/2010	iMGB1016657545	
Comments on Inspection:		DO NOT RELEASE. RULE 19.15.25.10. NEED TO REMOVE ELEC STUB POLE FROM WEST SIDE OF REMOVED PUMPING UNIT. ALSO NEED TO REMOVE TANK PAD CHECKING FOR CONTAMINATION AND LEVEL TO CONTOUR. REMOVE DRIP CONTAINMENT (1/2 OF STEEL BARREL) AND PIPING STICKING OUT OF GROUND. THIS IS 1ST LETTER OF NON-COMPLIANCE. MGB.					

QUEEN COM No.001				L-20-11S-33E	30-025-22642-00-00		
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.	
06/15/2010	Plugged Well Surface Restor	Maxey Brown	Yes	No	9/18/2010	iMGB1016656336	
Comments on Inspection:		DO NOT RELEASE. RULE 19.15.25.10. NEED TO REMOVE HEATER TREATER AND BASE, ALSO REMOVE TANK PAD CHECKING FOR CONTAMINATION AND LEVEL TO NATURAL CONTOUR. MARKER IS OKAY. THIS IS 1ST LETTER OF NON-COMPLIANCE.					

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




Hobbs OCD District Office

COMPLIANCE OFFICER

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data
*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



HASLER
017H15554612
\$0.440
06/17/2010
Mailed From 88240
US POSTAGE

JAY MANAGEMENT COMPANY, LLC
2425 WEST LOOP SOUTH, SUITE 810
HOUSTON, TX 77027