Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103 October 13, 2009	
<u>District I</u> 1625 N French Dr , Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	
District II		DIVISION	30-025-35662	
1301 W Grand Ave, Artesia NA 8824 CONSERVATION DIVISION District III 1000 Rio Brazos Rd, Aztec, NM 87410 Section For NM 87505		•	5. Indicate Type of Lease STATE FEE FEE	
District IV	6 2010 Santa Fe, NM 8	7505	6. State Oil & Gas Le	
District IV 1220 S. St Francis Dr , Santa Fe, WN 87505				
SUNDRAN	SOCO PICES AND REPORTS ON WELLS	3 7	7. Lease Name or Uni	t Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			State BD	/
1. Type of Well: Oil Well Gas Well Other			8. Well Number 4	
2. Name of Operator Samson Resources			9. OGRID Number 20165	
3. Address of Operator			10. Pool name or Wildcat	
200 N Loraine, Ste 1010, Midland, TX 79701			Bagley/Penr	1
4. Well Location				
Unit Letter H	: 1894 feet from the North			East line
Section 2	Township 12S Range		MPM Cour	ity Lea /
The state of the s	11. Elevation (Show whether DR 4232 G			
	7232 0	K	[[] [] [] [] [] [] [] [] [] [
12. Check	Appropriate Box to Indicate N	fature of Notice, Re	eport or Other Dat	a
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				ERING CASING
TEMPORARILY ABANDON				ND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT J	ОВ 🗌	
DOWNHOLE COMMINGLE				
OTHER:	, 🗆	OTHER: TA		\boxtimes
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
proposed completion of re	_			
12/15/09:	This Appro	oval of Temporar nent Expires	¥./>.	
POH w/ pkr.	Abandonn	nent Expires 5	-14-601	2
RU WL.				
Dump 36' cmt on CIBP @ 8695'. Set CIBP @ 8500', dump 35' cmt on top of CIBP.				
05/14/10:				
Test casing to 500 psi – run 30 min chart – down 5 psi to 555 psi. Csg tested ok – chart attached.				
	1	est of my lenovylodge o	nd haliaf	
I hereby certify that the information	above is true and complete to the be	est of my knowledge a	nd benef.	
da Ma	-	•		
SIGNATURE WELL MILLS	TITLE Op	erations Manager	DATE05/	11/2010
Type or print name Kenneth K	rawietz E-mail addres	s: <u>kkrawietz@samso</u>	n.com PHONE:	432-683-7063
For State Use Only		(5/5		
	/ ///	Ence m	2 <u>e</u> DATE	6-17-10
APPROVED BY	yahr TITLE -	SIFT IN	DATE_	6-17-10 Jan
Conditions of Approval (if any):	/			7.5K
				Χ.

