RECEIVED

עוט ל ז אטע HOBBSOCD

PlA'd. OK TO RELEASE. MUSS. 6/23/2010

Submit One Copy To Appropriate District Office	State of New Me	exico		Form C-103
District I	Energy, Minerals and Natu	ıral Resources		March 18, 2009
1625 N French Dr., Hobbs, NM 88240		WELL API NO.		
OIL CONSERVATION DIVISION 301 W Grand Ave., Artesia, NM 88210		30-025-39325		
District III	of W. Gland Ave., Artesia, 1441 66210		5. Indicate Type of Lease	
1000 Rio Brazos Rd , Aztec, NM 87410	Santa Fe, NM 87505		STATE X FEE	
District IV	Santa Fe, INIVI 8	/303	6. State Oil & Gas Lease l	No.
1220 S. St. Francis Dr , Santa Fe, NM 87505			VO-6326	
	ES AND REPORTS ON WELLS	3	7. Lease Name or Unit Ag	reement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Reba BNT State		
DIFFERENT RESERVOIR USE "APPLICAT	TION FOR PERMIT" (FORM C-101) FO	OR SUCH	8. Well Number	7
PROPOSALS) 1. Type of Well: Gas Well X Other PA		6. Well Halliber		
	as well X Other PA			
2. Name of Operator			9. OGRID Number	
Yates Petroleum Corporation			025575	
3. Address of Operator 105 S. 4 th Street, Artesia, NM 88210		10. Pool name or Wildcat	<i>'</i>	
		Llano; Upper Penn		
4. Well Location			,	
Unit Letter E: 2310 feet f	from the North line and 990	feet from the	Westline	
	S Range 35E NMPM	 Lea Cou		
	11. Elevation (Show whether DR)		<u> </u>	
11. Lievation (bnow whether Dit, idab, it), oit, etc./				
12. Check Appropriate Box to I	ndicate Nature of Notice R	Penart or Other	Data	
12. Check Appropriate Box to 1	nareate reature of rectice, re	coport of Other	Data	
NOTICE OF INTE	ENTION TO:	SUF	SEQUENT REPORT	OF·
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING				
TEMPORARILY ABANDON				
	MULTIPLE COMPL	CASING/CEMEN		`
FOLL ON ALTEN CASINO	VIOLETIFEE COMPE	CASING/CEIVIE	4130B L	
QTHER:	П	□ Location is	ready for OCD inspection af	ter P&Δ
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
Note: Per OCD instructions- use below ground steel plate with PA well information.				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR				
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
/	or manager of the	<u>arron</u>		
The location has been leveled as no	early as possible to original grou	and contour and ha	s been cleared of all junk, tras	h. flow lines and
other production equipment.	3 11 11 11 11 11 11 11 11 11 11 11 11 11			,
Anchors, dead men, tie downs and	risers have been cut off at least	two feet below gro	ound level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator	or's pit permit and closure plan.	All flow lines, pro	duction equipment and junk h	ave been removed
from lease and well location.				
All metal bolts and other materials	have been removed. Portable ba	ases have been rem	oved. (Poured onsite concrete	bases do not have
to be removed.)			,	
All other environmental concerns	have been addressed as per OCI	O rules.		
Pipelines and flow lines have been	abandoned in accordance with 3	19.15.35.10 NMA	C. All fluids have been remove	red from non-
retrieved flow lines and pipelines.				
Note: this is a rat hole fill.				
When all work has been completed, ret				
- / }	urn this form to the appropriate I	District office to so	hedule an inspection.	
1/1	urn this form to the appropriate I	District office to sc	hedule an inspection.	
last 10)				7
SIGNATURE AND THE				B-17-10
C . 4				3-17-10
SIGNATURE SIGNATURE SCOTT				6- <u>17-10</u> 575-365-4716
C . 4				<u>6-17-10</u> 675-365-4716
TYPE OR PRINT NAME Scott			in Supervisa DATE Com	3-17-10 575-365-4716
TYPE OR PRINT NAME Scott For State Use Only APPROVED BY:				6-17-10 575-365-4716 6/2 3 /2010
TYPE OR PRINT NAME Scott For State Use Only				6-17-10 675-365-4716 6/23/2010