

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

May 27, 2004

RECEIVED

OIL CONSERVATION DIVISION

1220 South St. Francis Dr.

Santa Fe, NM 87505

JUL 08 2010

HOBBSOCD

WELL API NO.

30-025-05668

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B-1651-9

7. Lease Name or Unit Agreement Name

NORTH MONUMENT G/SA UNIT BLK 6

8. Well Number

4

9. OGRID Number

873

10. Pool name or Wildcat

Eunice Monument G/SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

APACHE CORP.

3. Address of Operator

6120 S. YALE STE 1500 TULSA OK 74136

4. Well Location

Unit Letter D : 660' feet from the N line and 660' feet from the W lineSection 20 Township 19S Range 37E NMPM County LEA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3,673' DF

Pit or Below-grade Tank Application ☐ or Closure ☐Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water N/A

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐TEMPORARILY ABANDON ☐ CHANGE PLANS ☐PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐ P AND A ☒CASING/CEMENT JOB ☐OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Tag C.I.B.P. @ 3,732' Circulate well w/M.L.F.

06-11-10 Spot 25 sx on C.I.B.P.

06-11-10 Perf @ 2,580'. Could not get P.I.R. spot 30 sx @ 2,636'. W.O.C. Tag @ 2,475'.

06-14-10 Spot 50 sx 1,607' W.O.C. Tag @ 1,340'.

06-15-10 Perf @ 259' Sqz 75 sx to surface.

Move in and rig up: 06-10-10

Rig down move out: 06-15-10, cut off wth, anchors, & install dry hole marker.

Approved for plugging of well bore only.
Liability under bond is retained pending receipt
of C-103 (Subsequent Report of Well Plugging)
which may be found at OCD Web Page under
Forms, www.emard.state.nm.us/oed.I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☒, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.SIGNATURE Greg Bryant TITLE P&A Tech (Basic Energy Services) DATE 6/30/10

Type or print name: Greg Bryant

E-mail address:

Telephone No. 432-563-3355

For State Use Only

APPROVED BY: Greg Bryant TITLE STAFF MGR DATE 7-12-10

Conditions of Approval (if any):

P.m.