Form 3160-5 (August 2007)

UNITED STATES OCD-HOBBS

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

FORM A	PPRO	VED
OMB No	1004-	0137
Evniree I	oly 31	2010

	Expires	J
Lease Serial No.		
CUCSAEON		

	6. If Indian, Allottee or Tribe Name
İ	N/A

SUBMIT IN TRIPLICATE – Other instructions on page 2. 1. Type of Well Oil Well Gas Well Other Injection		7. If Unit of CA/Agreement, Name and/or No			
		Warren Unit 8. Well Name and No. Warren Unit B/T WF # 39			
2 Name of Operator ConocoPhillips Company			9. API Well No 30-025-25203	/	
3a. Address 3b. Phone No. (include area code) P.O. Box 51810 423-688-6943		10. Field and Pool or Exploratory Area Warren Blinebry/Tubb			
4. Location of Well (Footage, Sec , T., 660 FNL & 1980 FEL UL: B of 34-20S-38E	R ,M., or Survey Description	1)		11. Country or Parish, S Lea County, NM	State
12. CHEC	CK THE APPROPRIATE BO	OX(ES) TO INDICATE NATUR	E OF NOTI	CE, REPORT OR OTHE	ER DATA
TYPE OF SUBMISSION		Т	YPE OF AC	TION	
Notice of Intent	Acidize Alter Casing	Deepen Fracture Treat		duction (Start/Resume)	Water Shut-Off Well Integrity
✓ Subsequent Report	Casing Repair Change Plans	New Construction Plug and Abandon	Recomplete Temporarily Abandon		Other Hole in Tubing
Final Abandonment Notice	Convert to Injection	Plug Back	Wat	er Disposal	
13. Describe Proposed or Completed C the proposal is to deepen direction					

Workover: 5/17-24/2010:

determined that the site is ready for final inspection.)

MIRU. Unseat pkr. TOH w/tubing. Tested. Identified hole in tubing. Repaired. Cleaned out well. RIH w/pkr at set at 5816'. Load and test casing. Notified OCD of intent to pressure test. Ran MIT. Good test. RDMO.


Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has

RECEIVED

JUL 16 2010

HOBBSOCD

Sr Regula	tony Si	necialist						
			· · · · · · · · · · · · · · · · · · ·					
		EDIC.	D-EAD	DECC	ngn			
ORSTA		MAGE	USFUR	NEUL	טאונ			
Title	,,	1111	1 1 2	M1 Date		JUL	192	2010
Office		1	tin W	inkler	j		-	
nowingly and	willfal	IREALL OF	SAD FIELD	TOPFICE	ency of	he United	States ar	ny false
	06/24/2010 OR STA Title Office	06/24/2010 OR STA AF 0 Title	O6/24/2010 OR STA DE OFFRIE Title Office /s/ Dus	OR STA ACOFFICE USE OR Title Office /s/ Dustin W	OG/24/2010 OR STA DE OFFREDSE OR RECC Title Office /s/ Dustin Winkler	OR STANCOFFICE OSEOR RECORD Title Office /s/ Dustin Winkler	OR STATE OF THE DEFOR RECORD Title Office /s/ Dustin Winkler	O6/24/2010 OR STA AR OFFICE DISEOR RECORD Title JUL 1 4 2010 Pate 1 9 2



Warren Unit #39 NABORS CALLIBRATION DATE 3-26-10 SERIAL A 808 5-21-10 /1:40 PM gang Johnson PACKERS PICR DEPTH 5816 HABUS WIS