
Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103
Enough Minarala and Natural Desarrance		esources WELL AP	March 4, 2004
District I 1625 N French Dr., Hobbs, NM 88278 District II 1301 W. Grand Ave, Artesia, NM 88210 District III 1220 South St. Frencia Dr.		VISION 30-02	25-30966
District III 1000 Rio Brazos Rd, Aztec, NM 87410 UL 19 2011 220 South St. Francis Dr. Santa Fe. NM 87505		Or. 5. Indicate	e Type of Lease
District IV Santa Fe, NM 8741@UL 1 5 2010		6. State O	ATE FEE IIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII
1220 S St Francis Dr., Santa Fe, NMHOBBSOCD 87505			
SUNDRY NOTICES AND		7. Lease N	Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			ngton Unit
PROPOSALS) 1. Type of Well:		8. Well N	umber
Oil Well Gas Well Other		74	
Name of Operator Chevron Midcontinent, L.P.	1	9. OGRID 241333	Number
3. Address of Operator			ame or Wildcat
#15 Smith Rd., Midland, TX 79705 4. Well Location			Upper San Andres W
Unit Letter O: 180 feet from the South line and 2625 feet from the East line			
Section 4	Township 17-S Range 3	6-E NMPM	Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)			
Pit Location: UL O Sect 4 Twp 17-S Rng 36-E Pit type Steel Depth to Groundwater Distance from nearest fresh water well Over 1000			
Distance from nearest surface water Below-grade Tank Location ULSectTwpRng;			
180 feet from the South line and 2625 feet from the East line (Steel Tank)			
12. Check Appropria NOTICE OF INTENTIO PERFORM REMEDIAL WORK ☐ PLUG AN			Other Data T REPORT OF: ALTERING CASING
TEMPORARILY ABANDON CHANGE	EPLANS 🗌 COM	MENCE DRILLING OPNS	
PULL OR ALTER CASING MULTIPL COMPLE		ING TEST AND IENT JOB	ABANDONMENT
OTHER:	□ ОТН	ER:	П
13. Describe proposed or completed opera		•	ent dates, including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion			
or recompletion. 1 Notify OCD 24 hrs prior to MI and RU 2 RIH TAG PBTD@4670' and spot 25sx cement plug from 4670'-44 3. Displace hole w/MLF, 9 5# Brine w/12.5# gel P/BBL.	70'.		
 Spot 25sx cement plug from 3118'-2918' (B.Salt). WOC&TAG. Spot 25sx cement plug from 2105'-1905' (T.Salt). WOC&TAG. 			
 Perf and squeeze 130sx cement plug from 425'-surface (Fr.Wtr /si Install dryhole marker and clean location. 		The Oil Conservation Div	usion Must be notified
			ginning of plugging operations
I hereby certify that the information above is trugrade tank has been/will be constructed or closed accord	e and complete to the best of a ing to NMOCD guidelines [], a get	my knowledge and belief. Beral permit 🗌 or an (attached	I further certify that any pit or below- l) alternative OCD-approved plan □.
SIGNATURE M. La Kome	TITLE Agent	for Chevron USA, Inc.	DATE 7-16-2010
Type or print name M. Lee Roark	E-mail address:		Telephone No. 432-561-8600
(This space for State use)			
APPPROVED BY Conditions of approval, if any:	TITLE TI	AF MAR	DATE 7-19-10
Conditions of approval, if ally.			COA

WLU #74 API No. 30-025-30966



5-1/2" 15.5# CSG - set @ 5215' CMT w/ 1200 sks CIRC

TD = 5215

PLU0 # 7

MUOII

PLUGES

MICUM PLUG #

PLIKE #

TD <u>5215</u>

TT 1812

ANO

WC

MAR NWAST ATOKA MORROW

DEVOSEAN

CHARIOLIC