## MIB 7/20/2010

Office	State of New Mexico		Form C-103	
District I 1625 N. French Dr., Hobbs, NN CELVED  Energy, Minerals and Natural Resources		WELL API NO. 30-025-28715		
OIL CONSERVATION DIVISION  OIL CONSERVATION DIVISION			5. Indicate Type of	V
District III 1000 Rio Brazos Rd, Aztec, NM 87410 12 2010 1220 South St. Francis Dr. Santa Fe, NM 87505		STATE 6. State Oil & Gas	FEE X	
District IV 1220 S. St. Francis Dr., Santa Fe, MOBBSOCD 87505			o. State On & Gas	Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEFPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name Lister		
DIFTERENT RESERVOIR. USL "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)			<i>,</i>	
1. Type of Well: XOil Well Gas Well Other		8. Well Number 2 /		
2. Name of Operator Chesapeake Operating, Inc.			9. OGRID Numbe	r 147179
3. Address of Operator P.O. Box 18496 Oklahoma City, OK 73154-0496		10. Pool name or Wildcat Shoe Bar; Wolfcamp, North		
4. Well Location		Snoe Bar; Wollcan	ap, North	
Unit Letter B : 660' feet from the North line and 1830' feet from the East line				
Section 13 / Township 16S Range 35E NMPM County Lea  11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3966' GR				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASI				PORT OF: ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILL			.LING OPNS.□ I	P AND A
PULL OR ALTER CASING	PL [	CASING/CEMENT	JOB 🗌	
OTHER				
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.				
$\overline{X}$ A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the				
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR				
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.				
[X] The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and				
other production equipment.  X Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.				
[X] If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with				
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location.				
X All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have to be removed.)				
X All other environmental concerns have been addressed as per OCD rules.				
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-retrieved flow lines and pipelines.				
When all work has been completed, return this form to the appropriate District office to schedule an inspection.				
SIGNATURE Com Anna	TITLE_Se	nior Regulatory Cor	npl. Sp. L	DATE <u>07/09/2010</u>
TYPE OR PRINT NAME Bryan Arrant	E-MAIL:	bryan.arrant@chk.o	com PI	IONE: (405)935-3782
For State Use Only	_	١.	ODA.	
APPROVED BY: Maleur Shown Conditions of Approval (if any):	TITLE <u>C</u>	ompliane	e officer	DATE 7/20/201