

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88211  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

RECEIVED

JUL 20 2010

WELL API NO. 30 025 32839
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Caprock Maljamar Unit
8. Well Number 142
9. OGRID Number 270265
10. Pool name or Wildcat MALJ; G-SA

SUNDRIED REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input checked="" type="checkbox"/>	
2. Name of Operator SandRidge Exploration & Production, LLC	
3. Address of Operator 123 Robert S Kerr Ave, OKC OK 73102-6406	
4. Well Location Unit Letter <u>J</u> : <u>2544</u> feet from the <u>S</u> line and <u>2546</u> feet from the <u>E</u> line Section <u>17</u> Township <u>17S</u> Range <u>33E</u> NMPM LEA County <u>GL</u> <u>4206</u>	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: CLEAN OUT & ACIDIZE ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

6-11-10 MI RU PU.  
6-14-10 RU hot oiler. P/70 bbls hot wtr w/paraffin chem dn annulus. RD. Pld rods & pmp. ND WH, NU BOP. Pld tbg. Tgd @ 4458'.  
6-15/18-10 Ran bits & DCs. Tgd @ 4460'. RU reverse unit. Drld & cut 4460-4495. POH w/shoe; found pieces of tbg & end of bull plug.  
6-21-10 PU new shoe & 1 jt of WP. RIH w/DCs & jars. Cut 4492-4508. POH. Lost fish @ surface.  
6-22-10 RIH w/8 stds. Tgd @ 4437. Fell through & tagged again @ 4466'. Fell through & tagged @ 4510. POH w/overshot. No fish.  
Ran shoe & 2 jts WP, jars, & DCs on 2-7/8" tbg. Cut 4497-4514. POH w/shoe. Had metal pieces in it.  
6-23-10 PU & RIH w/mill, collar stabilizer & jars on 2-7/8" tbg. Milled metal 4499-4516. Circ hole clean.  
6-24-10 Tstd tbg to 6000 psi BIH. Ran pkr. RU Rising Star. A/perfs 4151-4516 w/6000 gals 15% NEFE w/2350# RS in 6 stgs. Pkr @ 4049' first 3 stgs. Max press 1380 psi. Max inj rate 4 BPM. Flushed w/24 bbls. Max press 2090 psi, Avg Rate 4 BPM. Opened well & bled dn. Set pkr @ 3920'. Loaded csg & press to 200 psi. P/final 3 stages. Max press 2090 psi, Avg Inj rate 4 BPM. F/60 bbls in 1 hr.  
6-25-10 Swbd well.  
6-28-10 Swbd 2 hrs. All load rec. FFL 2200'. RD swb unit. Pld pkr. RIH W/BHA & 135 jts 2-7/8" J-55 6.5# EUE prod tbg, set @ 4318'. ND BOP. NU WH.  
6-29-10 Ran pmp & rods. Loaded tbg w/6 bbls. Press to 500 psi w/pmp - OK. FL plugged. Hot oiled FL. RD PU. Returned to prod.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Terri Stathem TITLE Regulatory Manager DATE 7/16/10

Type or print name Terri Stathem E-mail address: tdstathem@sdrge.com PHONE: 405 429 5682

For State Use Only

APPROVED BY: [Signature] TITLE PETROLEUM ENGINEER DATE JUL 21 2010

Conditions of Approval (if any):