| Submit 3 Copies To Appropriate District Office | State of New Mexico Energy, Minerals and Natural Resources | Form C-103 June 19, 2008 |
|---|--|--|
| <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 | Energy, wither are and Natural Resources | WELL API NO. |
| <u>District II</u> 1301 W Grand Ave , Artesia, NM 88210 | OIL CONSERVATION DIVISION | 30-025-06728 |
| District III | 1220 South St. Francis Dr. | 5. Indicate Type of Lease STATE FEE X |
| 1000 Rio Brazos Rd., Aztec, NM 87410 District IV | Santa Fe, NM 87505 | 6. State Oil & Gas Lease No. |
| 1220 S. St. Francis Dr., Santa Fc, NM 87505 | | NA |
| SUNDRY NOTICE | ES AND REPORTS ON WELLS | 7. Lease Name or Unit Agreement Name |
| | LS TO DRILL OR TO DEEPĖN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH | Northeast Drinkard Unit |
| 1. Type of Well: ☐ Oil Well ☐ Gas Well ☑ Other: Injection Well | | 8. Well Number 808W |
| Name of Operator Apache Corporation | | 9. OGRID Number |
| 3. Address of Operator | , | 10. Pool name or Wildcat |
| 6120 S Yale Ave, Suite 1500, Tulsa, O | K 74136-4224 | Eunice; Bli-Tu-Dri-North (22900) |
| 4. Well Location | | |
| Unit Letter A : 660 | get from the North line and 660 | feet from the East line |
| Section 22 | Township 21S Range 37E | NMPM County Lea |
| | 11. Elevation (Show whether DR, RKB, RT, GR, etc. | |
| | | Company of the second of the s |
| 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data | | |
| | | |
| NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK □ PLUG AND ABANDON □ REMEDIAL WORK ☑ ALTERING CASING □ | | |
| PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ X ALTERING CASING ☐ TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A ☐ | | |
| <u> </u> | MULTIPLE COMPL CASING/CEMEN | |
| DOWNHOLE COMMINGLE | \ | |
| OTHER: | □ OTHER: | |
| 13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion | | |
| of starting any proposed work or recompletion. |). SEE RULE 1103. For Multiple Completions: At | tach wellbore diagram of proposed completion |
| Well failed previous MIT. | | |
| | | |
| 6/19 - 7/01/2009: Tag fill @ 5750'. CO fill to PBTD @ 6600'. Test packer, okay. RJH w/ injection equipment. Tubing @ 5606'. Packer @ 5608'. Circ packer fluid. Test held 500 psig for 30 minutes. | | |
| Notified OCD and ran MIT for OCD | 7/6/2009. Witnessed by Sylvia Dickey. | RECEIVED |
| | | |
| | | JUL 27 2010 |
| | | |
| | | HOBBSOCD |
| | | |
| Spud Date: | Rig Release Date: | |
| | | |
| X1 1 10 10 10 10 10 10 10 10 10 10 10 10 | | |
| I hereby certify that the information abo | ove is true and complete to the best of my knowledge | e and belief. |
| | | |
| SIGNATURE Sophie | Tackay TITLE Engineering Tech | DATE 08/03/2009 |
| Type or print name Sophie Mackay | E-mail address: sophle mackay@apac | hecorp.com PHONE: 918-491-4864 |
| For State Use Only | | |
| APPROVED BY: | alm TITLE STAFF MAT | DATE 7-27-10 |
| Conditions of Approval (if any): | 1 | DATE |

.

