Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
<u>District I</u> Ener	rgy, Minerals and Natural Resources	June 19, 2008 WELL API NO.
1625 N French Dr., Hobbs, NM 88240 District II		30-025-39709
District II  1301 W. Grand Avc., Artesia	GCONSERVATION DIVISION	5. Indicate Type of Lease
District III	1220 South St. Francis Dr.	STATE FEE 🗵
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	)	
SUNDRYMOTICES AND	• • • • • • • • • • • • • • • • • • • •	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DI DIFFERENT RESERVOIR USE "APPLICATION FOR PROPOSALS.)		West Blinebry Drinkard Unit (WBDU)
1. Type of Well:  Oil Well  Gas Well	Other:	8. Well Number <sub>118</sub>
2. Name of Operator		9. OGRID Number 873
Apache Corporation  3. Address of Operator		10. Pool name or Wildcat
6120 S Yale, Suite 1500 Tulsa, OK 74126-42	224	Eunice; Bli-Tu-Dr, North
4. Well Location		
Unit Letter J : 2330	feet from the South line and 24	30 feet from the East line
Section 17	Township 21S Range 37E	NMPM County Lea
	vation (Show whether DR, RKB, RT, GR, etc.	
3473' G	R `	
12. Check Appropria	ate Box to Indicate Nature of Notice,	, Report or Other Data
NOTICE OF INTENTION	ON TO:   SUE	SSEQUENT REPORT OF:
	ND ABANDON ☐ REMEDIAL WOR	
<del></del>		RILLING OPNS. P AND A
PULL OR ALTER CASING   MULTIP	PLE COMPL	NT JOB
DOWNHOLE COMMINGLE		
	ł	
	OTHER: Comple	tion
OTHER:  13. Describe proposed or completed operations.	ations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE	ations. (Clearly state all pertinent details, ar	
OTHER:  13. Describe proposed or completed operations.	ations. (Clearly state all pertinent details, ar	nd give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date
OTHER:  13. Describe proposed or completed operation of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-	ations. (Clearly state all pertinent details, and RULE 1103. For Multiple Completions: A	nd give pertinent dates, including estimated date ttach wellbore diagram of proposed completion
OTHER:  13. Describe proposed or completed oper- of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; P- 79', 87', 6706', 12', 14', 16', 18',	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 ho	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77',
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 159	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', oles)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion ', 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', oles)  S500'. Perf Tubb @ 6125', 27', 6203', 18', 20',
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97',	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Properators of the properators of t	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel;	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel;	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Proposition of the proposition of t	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160'	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Proposition of the proposition of t	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160'	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,66/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 516 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Proposition of the proposition of t	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160'	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,66/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 516 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles) 6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)
OTHER:  13. Describe proposed or completed oper- of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; P- 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21, 31, 47, 49, 51, 56, 58, 65, 69, 77, oles) 2500'. Perf Tubb @ 6125', 27, 6203', 18, 20, 6301', 07, 15, 23, 34, 39, 50 w/2 SPF (60) 136,727# 20/40 sand
OTHER:  13. Describe proposed or completed operators of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; Prop', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,66/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21, 31, 47, 49, 51, 56, 58, 65, 69, 77, oles) 2500'. Perf Tubb @ 6125', 27, 6203', 18, 20, 6301', 07, 15, 23, 34, 39, 50 w/2 SPF (60) 136,727# 20/40 sand
OTHER:  13. Describe proposed or completed oper- of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; P- 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE) 15.35; 202,653# 20/40 sand. RIH w/CBP @ 60', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21, 31, 47, 49, 51, 56, 58, 65, 69, 77, oles) 2500'. Perf Tubb @ 6125', 27, 6203', 18, 20, 6301', 07, 15, 23, 34, 39, 50 w/2 SPF (60) 136,727# 20/40 sand
OTHER:  13. Describe proposed or completed oper- of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry- 6/15/2010 PBTD @ 7160'; TOC @ 350'; P- 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes) 6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010	and give pertinent dates, including estimated date attach wellbore diagram of proposed completion 1, 21, 31, 47, 49, 51, 56, 58, 65, 69, 77, oles) 2500'. Perf Tubb @ 6125', 27, 6203', 18, 20, 6301', 07, 15, 23, 34, 39, 50 w/2 SPF (60) 136,727# 20/40 sand
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-6/15/2010 PBTD @ 7160'; TOC @ 350'; P 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)  6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 6', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010  Tue and complete to the best of my knowledge and complete to the best of my knowledge TITLE Sr. Engr Tech	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion (1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', bles)  2500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)  136,727# 20/40 sand  ge and belief.  DATE 07/07/2010
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-6/15/2010 PBTD @ 7160'; TOC @ 350'; P 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)  6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010  Thereby certify that the information above is the SIGNATURE Control of the SIGNATURE Co	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE) 15.35; 202,653# 20/40 sand. RIH w/CBP @ 60', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion (1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', oles)  6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)  136,727# 20/40 sand  ge and belief.  DATE 07/07/2010  Checorp com PHONE: 918/491-4853
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-6/15/2010 PBTD @ 7160'; TOC @ 350'; P. 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)  6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010  I hereby certify that the information above is to SIGNATURE Control of State Use Only	ations. (Clearly state all pertinent details, an RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE 3-35; 202,653# 20/40 sand. RIH w/CBP @ 60', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010  TITLE Sr. Engr Tech  E-mail address: reesa.holland@apace	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion (1, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', 50les)  2500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)  136,727# 20/40 sand  ge and belief.  DATE 07/07/2010  Checorp com PHONE: 918/491-4853
OTHER:  13. Describe proposed or completed oper of starting any proposed work). SEE or recompletion.  Apache completed this well in the Blinebry-6/15/2010 PBTD @ 7160'; TOC @ 350'; P 79', 87', 6706', 12', 14', 16', 18', 6/16/2010 Acidize Drinkard w/3000 gal 15' 6/17/2010 Frac Drinkard w/109,796 gal SS 23', 29', 31', 33', 45', 49', 57', 59 holes)  6/18/2010 Frac Tubb w/1554 gal acid; 56,6 6/21/2010 CO & DO CBP @ 6500' & CO to 6/22/2010 RIH w/2-7/8" tubing to 6794' 6/23/2010 Set 640 Pumping Unit and start  Spud Date:  05/04/2010  Thereby certify that the information above is the SIGNATURE Control of the SIGNATURE Co	ations. (Clearly state all pertinent details, at RULE 1103. For Multiple Completions: A Tubb-Drinkard.  erf Drinkard @ 6595', 6602', 07', 09', 17', 19 20', 22', 31', 35', 37', 39', 41' w/2 SPF (60 how NEFE) 1.35; 202,653# 20/40 sand. RIH w/CBP @ 60', 65', 67', 69', 71', 77', 82', 91', 93', 95', 97', 616 gal SS-25 & flush w/5922 gal linear gel; o PBTD @ 7160' producing.  Rig Release Date: 05/15/2010  Tue and complete to the best of my knowledge and complete to the best of my knowledge E-mail address: reesa.holland@apage.	nd give pertinent dates, including estimated date attach wellbore diagram of proposed completion (2, 21', 31', 47', 49', 51', 56', 58', 65', 69', 77', 50les)  6500'. Perf Tubb @ 6125', 27', 6203', 18', 20', 6301', 07', 15', 23', 34', 39', 50' w/2 SPF (60)  136,727# 20/40 sand  ge and belief.  DATE 07/07/2010  Checorp com PHONE: 918/491-4853