

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-HOBBS

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM115422

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE – Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

8. Well Name and No.
Ike Federal #1

2. Name of Operator
B C Operating, Inc.

9. API Well No.
30-025-38151

3a. Address
P O Box 50820
Midland, TX 79710

3b. Phone No. (include area code)
432-684-9696 ext 253

10. Field and Pool or Exploratory Area
Paducah, East Delaware

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
660' FSL & 660' FWL, Unit Letter M
Section 28, T25S-R32E

11. Country or Parish, State
Lea County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment Notice

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☒ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☐ Other

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

1. 3/8/10 MIRU. ND wellhead.
2. 3/9/10 RIH w/ CIBP to 4580', tag, circulate plugging mud, spot 25 sx Class C cement @ 4580.
3. 3/10/10 RIH spot 25 sx Class C cement @ 2943'.
4. 3/10/10 RIH spot 25 sx Class C cement @ 1569', WOC.
5. 3/10/10 Tag TOC @ 1306', spot 60 sx Class C cement from 556' to surface.
6. Cut off wellhead, cut off anchors, cover cellar.

Well is P&A'd.

Accepted as to plugging of the well bore.
Liability under bond is retained until
Surface restoration is completed.

RECEIVED

AUG 12 2010

HOBBSOCD

ACCEPTED FOR RECORD

AUG 6 2010

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Reclamation Due 9-10-10

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Tami Parker

Title Regulatory Analyst

Signature

Date 07/06/2010

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

DISTRICT 1 SUPERVISOR

AUG 13 2010

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

(Instructions on page 2)