Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, No. 1625 VED District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa FF, 10845 OCD SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			Form C-103 May 27, 2004
		WELL API NO.	
		30-025-106	
		5. Indicate Type of Le	
		STATE	TEL LAI
		6. State Oil & Gas Lea	se No.
		7. Lease Name or Unit	
1. Type of Well: Oil Well		8. Well Number	33, /
2. Name of Operator		9. OGRID Number	
CIMAREX ENERGY CO. OF COLORADO ATTN: ZENO FARRIS		162683	
3. Address of Operator		10. Pool name or Wildcat	
P.O. BOX 140907, IRVING, TEXAS 75014-0907 4. Well Location		LANGLIE MATTIX 7 R	IVERS-O-GRAYBURG
500			
Unit Letter M: reet from the S	OUTH line and	990 feet from th	e <u>WEST</u> line
Section 04 Township 238	Range 37E		ounty LEA
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3,328' DF			
Pit or Below-grade Tank Application or Closure \			
Pit type STEEL Depth to Groundwater 125' Distance from nearest fresh water well * Distance from nearest surface water *			
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material * NONE WITHIN 1,000'			
12. Check Appropriate Box to Indica NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON X	1	SEQUENT REPOR	
TEMPORARILY ABANDON	COMMENCE DRILLI		LUG AND X
PULL OR ALTER CASING MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB		
OTHER:	OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.			
PROPOSED PLUGGING PROCEDURE:			
1) TAG EXSITING 5-1/2" CIBP + CMT. @ +/-3,425'; CI 2) PERF. X ATTEMPT TO SQZ. A 45 SX. CMT. PLUG @ 2, 3) PERF. X ATTEMPT TO SQZ. A 75 SX. CMT. PLUG @ 1, 4) PERF. X ATTEMPT TO SQZ. A 35 SX. CMT. PLUG @ 42 5) PERF. X CIRCULATE TO SURFACE A 60 SX. CMT. PLUG 6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON S	510'-2,490'(B/SALT) 300'-1,085'(T/SALT) 0'-320'(8-5/8"CSG. @ 175'-3'. TEEL PLATE TO CASING	; WOC X TAG TOP OF O X T/ANHY.); WOC X TA SHOE).— WOC & TAG SS X INSTALL DRY HOLL	G TOP OF PLUG. (E MARKER.
I hereby certify that the information above is true and complete to the	e best of my knowledg	ge and belief. I further cer	tify that any pit or below-
grade tank has been/will be constructed or closed according to NMOCD guidel			
		EYLER@MILACRO-RES.CC	M
Telephone No. (432) 687–3033 For State Use Only			
APPROVED BY	TIE SAS	- MAP	8-17-10
Conditions of Assessed in	ILL	DATE	
THE ONE CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS			

