State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	NSERVATION DIVISION	Revised 3-27-2004
1625 N French Dr, Hobbs, NM 88240	CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505	WELL API NO 30-025-07599
DISTRICT II 1301 W Grand Ave, Artesia, NM 88210 DISTRICT III AUG 2 7 2010 AUG 2 7 2010	,	5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210		STATE FEE X
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410		6 State Oil & Gas Lease No
SUNDRY NOTICES AND REPOR	TS ON WELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		South Hobbs (G/SA) Unit
1 Type of Well Oil Well / Gas Well	Other Injector	8 Well No 34
2 Name of Operator	- Injector	9 OGRID No 157984
Occidental Permian Ltd. 3 Address of Operator		10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, TX 79323		TODBS (G/G/I)
4 Well Location		
Unit Letter H 1980 Feet From The N	North 660 Fee	et From The East Line
Section 4 Township	19-S Range 38-I	E NMPM Lea County
11. Elevation (Show w 3617' DF	rhether DF, RKB, RT GR, etc)	
Pit or Below-grade Tank Application or Closure		
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material		
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDO	N REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS	COMMENCE DRILLING OP	NS. PLUG & ABANDONMENT
PULL OR ALTER CASING Multiple Completion	CASING TEST AND CEMEN	NT JOB
OTHER:	OTHER: Coiled tubing	job X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
1. RU Coiled tubing unit.		
2. Break circulation and tag PBTD @4196'.		
3. Water wash perfs.4. Close backside in and acidize perfs with 2500 gal of 15%	UCI agid	,
5. Open backside & go to bottom. No circulation.		
6. RD Coiled tubing unit.		
RU 07/22/2010 RD 07/22/2010		
10 0112212010		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be		
constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved		
plan plan		
SIGNATURE NUNCLY OF TITLE Administrative Associate DATE 08/26/2010		
TYPE OR PRINT NAME Mendy A Johnson D-mai	l address: mendy_johnson@oxy.com	TELEPHONE NO 806-592-6280
For State Use Only	/ _	
APPROVED BY	TITLE OTHER	DATE 831-10
CONDITIONS OF APPROVAL JE ANY		