Form 3160 RECEIVED UNITED STATES FORM APPROVED OMB NO. 1004-0135 (August 2007) SEP 13 2010 DEPARTMENT OF THE INTERIOR OCD Hobbs Expires: July 31, 2010 **BUREAU OF LAND MANAGEMENT** HOBBS SONDRY NOTICES AND REPORTS ON WELLS 5. Lease Serial No. NMNM96244 Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals. 6. If Indian, Allottee or Tribe Name SUBMIT IN TRIPLICATE - Other instructions on reverse side. 7. If Unit or CA/Agreement, Name and/or No. Type of Well 8. Well Name and No. LIVESTOCK FEDERAL 9 2 Oil Well Gas Well Other Name of Operator LINDA GOOD API Well No Contact: CHESAPEAKE OPERATING, INC. E-Mail: linda.good@chk.com 30-025-36583 3b. Phone No. (include area code) Ph: 405-935-4275 10. Field and Pool, or Exploratory BOOTLEG RIDGE MORROW P.O. BOX 18496 OKLAHOMA CITY, OK 73154-0496 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 9 T22S R33E SWNE 1450FNL 1950FEL LEA COUNTY, NM 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION ☐ Acidize ☐ Water Shut-Off Deepen Production (Start/Resume) Notice of Intent ☐ Alter Casing Fracture Treat ☐ Reclamation ☐ Well Integrity ☐ Subsequent Report Casing Repair New Construction ☐ Recomplete Other Final Abandonment Notice ☐ Change Plans □ Plug and Abandon ☐ Temporarily Abandon Convert to Injection ☐ Plug Back ■ Water Disposal 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) determined that the site is ready for final inspection.) CHESAPEAKE, RESPECTFULLY, REQUESTS, PERMISSION AND A QUICK APPROVAL TO SET A PLUG AND ABANDON THE MORROW PERFS TODAY PER THE FOLLOWING PROCEDURE. Hold PJSA prior to beginning work each morning and as required for specific operations. 1. Prep location. Check anchors and clean area for workover. SEE ATTACHED FOR 2. MIRU workover rig. ND WH. NU 10K BOPs and test. CONDITIONS OF APPROVAL 3. RU wireline and RIH w/gauge ring and junk basket to 14,515'. 4. RIH w/4-1/2" CIBP and set @ +/- 14,368' and dump 35' cement on top. 14 I hereby certify that the foregoing is true and correct. Electronic Submission #92328 verified by the BLM Well Information System For CHESAPEAKE OPERATING, INC., sent to the Hobbs Name (Printed/Typed) LINDA GOOD SR. REGULATORY COMPLIANCE SPEC Signature (Electronic Submission) 09/07/2010 THIS SPACE FOR FEDERAL OR STATE OFF T SUPER SEP 1 3 2010 YERAL MAHACES Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject leave which would entitle the applicant to conduct operations thereon. 7 2010 SEP s/ Dustin Winkler Office Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and with the make the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

CARLSBAD FIELD OFFICE

CARLSBAD FIELD OFFICE

Additional data for EC transaction #92328 that would not fit on the form

32. Additional remarks, continued

- 5. Load well with packer fluid.
- $6.\ Pressure\ up\ well\ to\ 500\ psi.\ Record\ MIT\ for\ 30\ minutes.$ If less than 10% pressure change in 30 minutes MIT is acceptable.
- 7. Prep to LD 4-1/2" RTS6 WS. POH LD 4-1/2" RTS6 WS. Rotate and sting out of the FA-1 Baker Pkr and seal assembly.
- 8. ND BOP. NU WH.
- 9. RDMO. Clean location.

WELLBORE DIAGRAM ATTACHED.

(CHK PN 819494)

Workover Proposal Chesapeake

LIVESTOCK FEDERAL 2-9

Field: Bootleg Ridge E.

County: LEA

NEW MEXICO State:


Location:

Elevation: GL 3,619.0 KB 3,644.0

KB Height: 25.0

Spud Date: 4/3/2004 Initial Compl. Date: API#: 3002536583 CHK Property #: 819494 1st Prod Date: 8/14/2004 PBTD: Original Hole - 14515.0

TD: 15,400.0



Page 1/1

Chesapeake Operating, Inc. NM-96244: Livestock Federal 9 #2 API: 30-025-36583 Lea County, New Mexico

RE: Plug-Back – Conditions of Approval

There is to be no surface disturbance beyond the originally approved pad. A closed loop system is to be used. H2S monitoring and protection equipment is to be on site.

10M BOP is to be used for this well. All blowout preventer (BOP) and related equipment (BOPE) shall comply with well control requirements as described in Onshore Oil and Gas Order No. 2 and API RP 53 Sec. 17.

Cement on top of CIBP is to be Class H.

Plans to plug or produce this well to be received within 60 days.

Submit subsequent report once work is completed.

DHW 090710