Submit 1 Copy To Appropriate RECEIVED State of New Mexico Office District 1 Energy, Minerals and Natural Resources	Form C-103
1625 N. French Dr. Hobbs NM 88240	WELL API NO.
1301 W. Grand Ave. Artesia, NM 88710 OIL CONSERVATION DIVISION	30-025-01005
1000 Rio Bruzos Rd Aziec NACE NACE NACE NACE NACE NACE NACE NACE	5. Indicate Type of Lease STATE FEE \
District IV 1220 S St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	Kelsay
Type of Well: Oil Well	8. Well Number #1
Jay Management Company LLC	9. OGRID Number 247692
3. Address of Operator	10. Pool name or Wildcat
2425 West Loop South, Ste 810 Houston, TX 77027 4. Well Location	Bagley Permo Penn North
1	
Social and T	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	NMPM Lea County
4942' KB	
12. Check Appropriate Box to Indicate Nature of Notice, I	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	☐ ALTERING CASING ☐
DILL OR ALTER CLOSES	
DOWNHOLE COMMINGLE	10R []
OTHER:	
	give portions dates in al. 1'
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of	
proposed completion or recompletion. Proposed Start Date: 08/31/10	
Proposed Plans: RU & pull tubing out of the hole (possible fish out parted tubing). Per	in cotting and the state of the
Proposed Plans: RU & pull tubing out of the hole (possible fish out parted tubing). Begin setting cement plugs at below intervals: Plug #1: Perforate & squeeze cement @ 9960'. WOC & tag. Plug #3: Perforate & squeeze cement @ 5000'. WOC & tag.	
Plug #4: Perforate & squeeze cement @ 5000'. WOC & tag.	
Plug #4: Perforate & squeeze cement @ 3820" (bottom of 9-5/8" shoe). WOC & tag. PERF @ 3870 Plug #5: Perforate & squeeze cement @ 1600' (for salt plug). WOC & tag.	
Ping #6: Perforate & squeeze cement @ 375' (Bottom of 13-3/8" Casing) WOC & tag PERF(a) 4.75'	
Plug #7: Perforate & squeeze cement @ 60'. WOC & Tag. Plug #8: Set 10' cement plug at surface.	
CT 1 200 COM I DIMO DOT 25' (MT DP SPOT 75 SVS OMT	
SET CIBP@ 9272', DUMP BAIL 35'CMT DR SPOT Z5 5X5 CMT. Condition of Approval: the operator shall give 24 hour	
notice to the app	pproval: the operator shall give 24 hour spropriate District office before work begins
,	
Spud Date: Rig Release Date:	
Kig Kelease Date.	
I hereby certify that the information above is true and complete to the best of my knowledge.	and belief.
SIGNATURE DATE: 08/22/10	
Type or print name: Kirk Broussard E-mail address: kirkb@isramco-jay.com sgrisham@is	
For State Use Only	
APPROVED BY: Maley Hown TITLE Compliance Office DATE 9/15/2010 Conditions of Approval (if day)	
1 (i) arrayy	

Jay Management Co. LLC

Kelsay #1 - Bagley Field M-28-11S-33E Lea Co, NM API #: 30-025-0100503820

Current Well Bore Diagram

