Submit 3 Copies To Appropriate State of New Mexico District Office Energy, Minerals and Natural Resources	Form C-103 May 27, 2004
1625 N French Dr., Hobbs, NM 88240	WELL API NO. /
District II 1301 W Grand Ave., Artesia, NM OIL CONSERVATION DIVISION	30-025-32342 /
88210 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE T FEE X
1000 Rio Brazos Rd., Azfec, NM Santa Fe, NW 07505	6. State Oil & Gas Lease No.
87410 District IV SEP_ 1.5, 2010	
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Name /
PROPOSALS.)	SOUTH JUSTIS UNIT
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other 🖌	8. Well Number F-14
2. Name of Operator LEGACY RESERVES OPERATING LP	9. OGRID Number 240974 /
3. Address of Operator P.O. BOX 10848	10. Pool name or Wildcat
MIDLAND, TX 79702	JUSTIS-BLINEBRY-TUBB-DRINKARD
4. Well Location	•
Unit Letter N: 450 feet from the SOUTH line and 2010 feet from the WEST line.	
Section 12 Township T25S Range R37E NMPM LEA County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3094' GR	
Pit or Below-grade Tank Application I or Closure I Pit typeDepth to GroundwaterDistance from nearest frsh water wellDistance from nearest surface	
water	
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls: Construction Material
	,
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING FEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A	
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	
OTHER Plugback, ESP Pump Test & Install Rod Pump 🛛 OTHER:	П
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including	
estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore	
diagram of proposed completion or recompletion.	
Estimated Start Date: 10/15/10	
MIRU pulling unit. Install BOP. POH w/ P-6, 600 BPD ESP and 23	3/8" production tubing. RIH w/ 5 ½"
RBP. Set RBP at 5365'. RU Centrilift ESP tech and spooler. RIH w/	P-6, 600 BPD ESP and 2 3/8"
production tubing. Set btm of ESP motor at 30' +/- above RBP at 5235'+/ ND BOP. Flange up wellhead.	
RDMO pulling unit. Start well pumping for 30-45 day test . MIRU pull	ng unit. Install BOP. RU Centrilift
ESP tech and spooler. POH w/ P-6, 600 BPD ESP and 5013' 2 3/8" RIH w/ tbg and RBP retrieving head. POH w/ RBP. RIH w/ CIBP. S	et CIBP at 5365'. RIH w/ pump,
rods and 2 3/8" production tubing. ND BOP. Flange up wellhead. R	DMO pulling unit. Start well pumping
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines [], a general permit [] or an (attached) alternative OCD-approved plan [].	
SIGNATURE Kerthinim TITLE: SR. PETROLEUM ENGINEE	
	RDATE09/14/2010
Type or print name KENT WILLIAMS E-mail address: For State Use Only	Telephone No. <u>(432) 689-5200</u>
APPROVED BY: TITLE PETROLEUM ENVIRUEN	SEP 1 6 2010
BY:TITLE_TITLE_TITLE_TITLE_TITLE_TITLE_TITLE_TITLE_TITLE_TTTTTTTTTT	DATE

R* -