

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
New Mexico Oil Conservation Division, District
1625 N. French Drive
Hobbs, NM 88240

FORM APPROVED
OMB NO 1004-0135
Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
 OXY USA Inc. / 16696

3a. Address
 P.O. Box 50250, Midland, TX 79710-0250

3b. Phone No (include area code)
 432-685-5717

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
 660 FSL 660 FEL SESE(P) Sec 29 T7S R36E

5. Lease Serial No.
 NM0321281

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No
 Todd Lower SA Unit

8. Well Name and No.
 #296

9. API Well No
 30-041-20239

10. Field and Pool, or Exploratory Area
 Todd Lower San Andres Assoc

11. County or Parish, State
 Roosevelt NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)

TD-4363' PBD-4346' Perfs-4305-4319'

8-5/8" 24# @ 330' w/ 250sx, 12-1/4" hole, TOC-Surf-Circ
 4-1/2" 9.5# csg @ 4363' w/ 300sx, 7-7/8" hole, TOC-2363'-Calc

Circ Hole w/ 10# MLF and between plugs

1. RIH & Set CIBP @ 4255' M&P 25sx cmt
2. M&P 25sx cmt @ 3600-3460'
3. Perf @ 2450' sqz 45sx cmt to 2325' WOC-Tag
4. Perf @ 2050' sqz 45sx cmt to 1930' WOC-Tag
5. Perf @ 1200' sqz 45sx cmt to 1080' WOC-Tag
6. Perf @ 380' sqz 140sx cmt to surface.

RECEIVED

SEP 17 2010

HOBBSOCD

APPROVED FOR 3 MONTH PERIOD
ENDING DEC 14 2010

14. I hereby certify that the foregoing is true and correct
 Name (Printed/Typed) David Stewart Title Sr. Regulatory Analyst
 Date 9/10

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by /S/ DAVID R. GLASS Title PETROLEUM ENGINEER Date SEP 14 2010
 Conditions of approval, if any, are attached Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon


Title 18 U.S.C. Section 1011 and Title 42 U.S.C. Section 12101 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious, or fraudulent statements or representations as to any matter within its jurisdiction.

SEE ATTACHED FOR CONDITIONS OF APPROVAL

OXY USA Inc. - Proposed
Todd Lower SA Unit #296
API No. 42-041-20239

140sx @ 380'-Surface

12-1/4" hole @ 330'
8-5/8" csg @ 330'
w/ 250sx-TOC-Surf-Circ



Perf @ 380'

45sx 1200-1080' WOC-Tag



Perf @ 1200'

45sx 2050-1930' WOC-Tag



Perf @ 2050'

45sx 2450-2325' WOC-Tag



Perf @ 2450'

25sx @ 3600-3460'



7-7/8" hole @ 4363'
4-1/2" csg @ 4363'
w/ 300sx-TOC-2363'-Calc

CIBP @ 4255' w/ 25sx




Perfs @ 4305-4319'

PB-4346'

TD-4363'

OXY USA Inc. - Current
Todd Lower SA Unit #296
API No. 42-041-20239

12-1/4" hole @ 330'
8-5/8" csg @ 330'
w/ 250sx-TOC-Surf-Circ



7-7/8" hole @ 4363'
4-1/2" csg @ 4363'
w/ 300sx-TOC-2363'-Calc

PB-4346'

TD-4363'

Perfs @ 4305-4319'

BUREAU OF LAND MANAGEMENT

Roswell Field Office
2909 West Second Street
Roswell, New Mexico 88201
(575) 627-0272

Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within **ninety (90)** days from the approval date of this Notice of Intent to Abandon. **If you are unable to plug the well by the 90th day provide the BLM Roswell Field Office, prior to the 90th day, with the reason for not meeting the deadline and a date when the BLM Roswell Field Office can expect the well to be plugged. Failure to do so will result in enforcement action.**
2. **Notification:** Contact the BLM Roswell Field Office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, during office hours call (575) 627-0205 or after office hours call (575) 420-2832. Engineer on call during office hours phone (575) 627-0275 or phone (after hours) call (575) 626-5749.
3. **Blowout Preventers:** A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The minimum BOP requirement is a 2M system for a well not deeper than 9090 feet; a 3M system for a well not deeper than 13636 feet; and a 5M system for a well not deeper than 22727 feet.
4. **Mud Requirement:** Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at a rate of 25 sacks (50 pounds each) of gel per 100 barrels of water. Minimum nine (9) pounds per gallon.
5. **Cement Requirement:** Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. In lieu of a cement plug in cased hole, a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 50 feet of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient.

Unless otherwise specified in the approved procedure, the cement plug shall consist of either class "C" for up to 7500 feet of depth, mixed at 14.8 lbs./gal with 6.3 gallons of fresh water per sack or class "H" for deeper than 7500 feet plugs, mixed at 16.4 lbs./gal with 4.3 gallons of fresh water per sack.

6. **Monument:** Upon abandonment of the well, all casing shall be cut-off at the base of the cellar or 3-feet below final restored ground level (whichever is deeper). The well bore shall then be covered with a metal plate at least ¼ inch thick and welded in place. The following information shall be permanently inscribed on the dry hole marker: Well name and number, the name of the operator, the lease serial number, the surveyed location (the quarter-quarter section, township and range or other authorized survey designation acceptable to the authorized officer; such as metes and bounds).
7. **Subsequent Plugging Reporting:** Within 30 days after plugging work is completed, file one original and five copies of the Subsequent Report of Abandonment, Form 3160-5 to the BLM Roswell Field Office. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**

Following the submittal and approval of the Subsequent Report of Abandonment, a Notice of Intent for Final Abandonment with the proposed surface restoration procedure must be submitted for approval.