

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

OCD-HOBBS SEP 28 2010
HOBBS

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NM 90161

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well ☐ Gas Well ☒ Other Injection Well

2. Name of Operator
Apache Corporation

3a. Address
6120 S Yale Ave, Suite 1500
Tulsa, OK 74136-4224

3b. Phone No. (include area code)
918-491-4864

7. If Unit of CA/Agreement, Name and/or No.

8. Well Name and No.
West Blinebry Drinkard Unit #41

9. API Well No.
30-025-06434

10. Field and Pool or Exploratory Area
Eunice; Bli-Tu-Dri, North (22900)

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
1980 FSL & 660 FEL
UL I, Sec 8, T21S, R37E

11. Country or Parish, State
Lea County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
☒ Subsequent Report	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	☐ Well Integrity
☐ Final Abandonment Notice	☐ Casing Repair	☐ New Construction	☐ Recomplete	☐ Other
	☐ Change Plans	☐ Plug and Abandon	☐ Temporarily Abandon	
	☒ Convert to Injection	☐ Plug Back	☐ Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

5/19/09 MIRU. POOH w/ pumping equipment.
5/20 - 5/28/09 Tag fill @ 6649' and DO to PBTD @ 6767', circ clean.
5/29/09 Perf Drinkard @ 6643-50, 6656-62, 6668-72, 6678-80, 6695-6706; 6718-20, 6730-36', 2 SPF, 88 holes.
5/29/09 Re-Perf Blinebry @ 5903, 5906, 5923, 5927, 5946, 5952, 5964, 5976, 5988, 5997, 6014, 6016', 2 SPF, 24 holes.
6/01/09 Isolate and acid existing Drinkard perms fr/ 6539' - 6629' w/ new Drinkard perms fr/ 6643' - 6736' w/ 4000 gals HCl.
6/01/09 Isolate and acid existng Blinebry perms fr/ 5667' - 5882' w/ new Blinebry perms fr/ 5903' - 6016' w/ 4000 gals HCl.
6/02/09 Set injection packer @ 5600'.
6/03/09 Set 2-3/8" injection tubing @ 5598'.
6/04/09 Run MIT, okay.
6/11/09 Run MIT, witnessed by OCD, chart attached, well shut in pending installation of injection lines.
8/03/09 Begin injection in the Blinebry/Drinkard.

RECEIVED FOR RECORD

SEP 26 2010

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

S Mackay

Title Engineering Tech

BUREAU OF LAND MANAGEMENT
CARLSBAD FIELD OFFICE

Signature

S. Mackay

Date 09/13/2009

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

ELG 9-29-10

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)