Submit 3 Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources	Form C-103 June 19, 2008
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-11617 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd., Aztec, NM 87410 1220 South St. Francis Dr.	STATE   FEE
District IV Santa Fe, NM 87505 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name South Langlie Jal Unit
1. Type of Well: Oil Well Gas Well Other	8. Well Number 17
2. Name of Operator B C Operating, Inc	9. OGRID Number
3. Address of Operator	160825 10. Pool name or Wildcat
P O Box 50820 Midland, TX 79710	Langlie Mattix Seven Rivers-Queen-GB
4. Well Location	
Unit Letter <u>H</u> : 2310' feet from the <u>North</u> line and <u>330'</u> feet from the <u>East</u> line	
Section 18 Township 25S Range 37E	NMPM Lea County
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3090' RT	A STATE OF THE STA
Control of the Contro	
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBS	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK	
TEMPORARILY ABANDON	LLING OPNS. D P AND A
PULL OR ALTER CASING	JOB []
_	
OTHER OTHER	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated dates of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completions.	
or recompletion.	
1 PHI/ CIPD/ C 22011	
<ol> <li>RIH w/ CIBP set @ 3321', tagged plug, circulate plugging mud, spot 45 sx on top of CIBP, WOC, tagged plug at 2969'.</li> <li>Spot 25 sx @ 2681'. TOH to WOC.</li> </ol>	
3. Perf @ 1250'. Squeeze with 50 sx cmt @ 1050'. TOH to WOC. Tagged cmt squeeze at 1120'.	
4. Perf @ 366' & circulate 145 sx from 366' to surface, inside and outside 5-1/2" casing. WOC overnight.	
<ul> <li>5. Tag cmt plug at 17'. Spot 10 sx cmt from 17' to surface.</li> <li>6. Dig out cellar, cut off wellhead and anchors, installed P&amp;A marker, cleaned location. Well work complete 9/22/2010.</li> </ul>	
5. 2-15 out totall, out off wormed and anothers, instance I &A marker, citation location. We	en work complete 9/22/2010.
Approved for plugging of well bore only Liability under bond is retained pending	
of C-103 (Subsequent Report of Well Pl	ugging)
which may be found at OCD Web Page of Forms, www.cmnrd.state.nm.us/ocd.	under
Sand Page 2/22/07	<del></del>
Spud Date:   2/22/07   Rig Release Date:   3/21/07	
I hereby certify that the information above is true and complete to the best of my knowledge	and halise
A second that the second to the desired to the best of my knowledge	and benef.
SIGNATURE Agan Walley TITLE Operations Manager	
SIGNATURE TITLE Operations Manager	DATE9/28/2010
Type or print name Jason Wacker E-mail address: jwacker@blackoakre	s.com PHONE: (432) 684-9696
For State Use Only	
APPROVED BY TITLE STAFF MG	DATE 9-29-10
Conditions of Approval (if any):	, , , , ,