Submit 3 Copies To Appropriate District	State of New	Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 87240 District II	Energy Minerals and Na	atural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240			WELL API NO. 30-025-36571
District II 1301 W. Grand Ave , Artesia, NM 88216 District III	OIL CONSERVATI	ON DIVISION	30-025-36571 5. Indicate Type of Lease
District III	EF 30 2019220 South St.	Francis Dr.	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	OBBSOCD Santa Fe, NA	4 87505	STATE: FEE X :
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87	505		6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			7. Lease Name or Unit Agreement Name: Resler B
PROPOSALS.) 1. Type of Well: Oil Well \(\overline{\times} \) Gas Well \(\overline{\to} \) Other			8. Well Number
2. Name of Operator			ζ.
OXY USA Inc.			9. OGRID Number 16696
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 50250 Midland	<u>, TX 79710-0250</u>		Langlie Mattix 7Rvr Qn-GB
4. Well Location			
Unit Letter0:_	660feet from the	south line and	1980 feet from the east line
Section 20	Township 23S	Range 37E	NMPM County Lea
	11. Elevation (Show wheth	er DR, RKB, RT, GR, et 3302'	tc.)
Pit or Below-grade Tank Application	or Closure		
		resh water well Di	stance from nearest surface water
			on Material
	Join Grade Park. York	one	on material
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK] PLUG AND ABANDON $oxed{X}$	REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING	MULTIPLE COMPLETION	CASING TEST AND CEMENT JOB	
OTHER:		OTHER:	
13. Describe proposed or comple	ted operations. (Clearly state all	pertinent details, and giv	e pertinent dates, including estimated date
of starting any proposed work	k). SEE RULE 1103. For Mult	iple Completions: Attacl	wellbore diagram of proposed completion
or recompletion. TD-3700' PBTD-3634' Perfs-3251-3258' 3510-3524'			
8-5/8" 24# csg @ 1123' w/675sx, 12-1/4" hole, TOC-Surf-Circ			
4-1/2" 11.6# csg @ 3700' w/1090sx, 7-7/8" hole, TOC-Surf-Circ			
1. RIH & Set CIBP @ 3210' w/ 25sx cmt			
2.	M&P 25sx cmt @ 2675-2425'	WOC-Tag	
	M&P 25sx cmt @ 1275-1025'	WOC-Tag	Must be notified
4.	M&P 30sx cmt @ 300'-Surfac	ce	onservation Division Must be notified prior to the beginning of plugging operations
	Circ 10∦ MLF between plu	igs The Oil Co	prior to the beginning
		24 1100.5	
I hereby certify that the information grade tank has been/will be constructed of	above is true and complete to to closed according to NMOCD guide	he best of hy Kilowledge	and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
//. <i>(</i>			
SIGNATURE VA'S			$\mathcal{D}H$
Type or print name David Stewa		E-mail address:	david_stewart@oxy.com Telephone No. 432-685-5717
For State Use Only	2111/11	DISTRICT 1	SUPERVISOR OCT 0 1 2010
APPROVED BY	y W. Hil	TITLE	DATE DATE
Conditions of Approval, if any:	J		()

OXY USA Inc. - Proposed Resler B #2 30-025-36571


30sx @ 300'-Surface

12-1/4" hole @ 1123' 8-5/8" csg @ 1123' w/ 675sx-TOC-Surf-Csg

25sx @ 1275-1025' WOC-Tag

25sx @ 2675-2425' WOC-Tag

CIBP @ 3210' w/ 25sx




Perfs @ 3251-3258'-2004 sqz w/ 50sx

Perfs @ 3510-3524'

7-7/8" hole @ 3700' 4-1/2" csg @ 3700' w/ 1090sx-TOC-Surf-Circ

PB-3634'

OXY USA Inc. - Current Resler B #2 30-025-36571



12-1/4" hole @ 1123' 8-5/8" csg @ 1123' w/ 675sx-TOC-Surf-Csg

Perfs @ 3251-3258'-2004 sqz w/ 50sx

Perfs @ 3510-3524'

7-7/8" hole @ 3700' 4-1/2" csg @ 3700' w/ 1090sx-TOC-Surf-Circ

PB-3634'