State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

FILE IN TRIPLICATE	OIL CONSERV	ATION DIVISION	,
<u>DISTRICT I</u> 1625 N French Dr , Hobbs, NM 88240	RECEIVE 1220 South	St. Francis Dr. NM 87505	WELL API NO 30-025-26935
DISTRICT II	SEP 3 0 2010		5 Indicate Type of Lease
1301 W Grand Ave, Artesia, NM 88210			STATE X FEE
DISTRICT III 1000 Rio Brazos Rd, Aztec, NM 87410	HOBBSOCD		6 State Oil & Gas Lease No
SUNDRY N	OTICES AND REPORTS ON WE	ELLS	7 Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (Form C-101) for such proposals)		North Hobbs (G/SA) Unit	
1 Type of Well	APPLICATION FOR PERMIT (Form C-	101) for such proposals)	Section 30 8. Well No 232
Oil Well	Gas Well Other In	jector	232
2 Name of Operator			9 OGRID No. 157984
Occidental Permian Ltd. 3 Address of Operator			10 Pool name or Wildcat Hobbs (G/SA)
HCR 1 Box 90 Denver City, T	'X 79323		
4 Well Location			,
Unit Letter K 1400	Feet From The South	Fee	et From The West Line
Section 30	Township 18-S	Range 38-	E NMPM Lea County
	11 Elevation (Show whether DF, R 3650' GL	KB, RT GR, etc)	
Pit or Below-grade Tank Application or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water			
Pit Liner Thickness mil Below-Grade Tank: Volume bbls; Construction Material			
12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING OF	PNS. PLUG & ABANDONMENT
PULL OR ALTER CASING	Multiple Completion	CASING TEST AND CEMEI	NT JOB
OTHER		OTHER: Clean out/OA	AP/Acid Treat X
13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any			
proposed work) SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 1. RUPU & RU. RUPU 07/26/10 RDPU 08/03/10			
2. ND wellhead/NU BOP.			
3. POOH w/tubing and injection equipment.			
4. RIH w/bit. Tag @4302' PBTD. POOH w/bit.5. RU wireline and perforate casing @4252-62', 4266-78' RD wireline.			
6. RIH w/SPA packer set @4024'. RU HES & acid treat well w/2520 gal of 15% NEFE acid. Flush with 50 bbl of 10# brine. RD HES. POOH			
w/SPA packer.		,,,,,	
7. ND BOP/NU C-PROX wellhead			
8. RIH w/dual injection packers set9. Test casing to 570 PSI for 30 mir			94119. KTC Hydraulic Tandem pkr set @4184'.
10. RDPU & RU. Clean location at		ark wintakei withhoeb on	Site for test.
	-		
I hereby certify that the information above constructed or	is true and complete to the best of my know	vledge and belief. I further certify	that any pit or below-grade tank has been/will be
closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved			
plan plan			
SIGNATURE YUNGY AMMINISTRATIVE Associate DATE 09/29/2010			
TYPE OR PRINT NAME Mendy A.	· · · · · · · · · · · · · · · · · · ·		
	Johnson E-mail andress:	mendy_johnson@oxy.com	TELEPHONE NO 806-592-6280
For State Use Only	Johnson E-mail andress:		
For State Use Only APPROVED BY	Johnson E-mail address:		1 TELEPHONE NO 806-592-6280 DATE 10-4-10

