

Submit 3 Copies To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources  
**RECEIVED**  
OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
**SEP 29 2010**  
**HOBBSOCD**

Form C-103  
June 19, 2008

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20195 ✓
1. Type of Well: <input checked="" type="checkbox"/> Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other: ✓		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/> ✓
2. Name of Operator Apache Corporation ✓		6. State Oil & Gas Lease No. NA
3. Address of Operator 6120 S Yale Ave, Suite 1500, Tulsa, OK 74136-4224 ✓		7. Lease Name or Unit Agreement Name Crown ✓
4. Well Location Unit Letter B : 330 feet from the North line and 2310 feet from the East line Section 13 Township 20S Range 38E NMPM County Lea		8. Well Number 001 ✓
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3543' GR		9. OGRID Number 873 ✓
		10. Pool name or Wildcat House; Blinbry, S / House; Tubb ✓

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:  
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐  
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐  
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐  
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:  
REMEDIAL WORK ☐ ALTERING CASING ☐  
COMMENCE DRILLING OPNS. ☐ P AND A ☐  
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: Recompletion Procedure ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Operator Oversight  
3/7/07 - 4/5/07

MIRU. POOH production equipment. Set CBP @ 6650'. Isolate csg lk fr/ 4413' - 4445'. Squeeze w/ 150 sx cmt. DO cmt. DO CBP @ 6650'. Perf Blinbry @ 6039-53, 6100-04, 6140-48, 6192-95', 2 SPF. Set RBP @ 6302' and packer @ 5985'. Acid Blinbry w/ 3000 gals 15% HCl. Swabbed and found 10% oil cut and good gas. Moved packer from 5985' to 5904'. Frac Blinbry w/ 50K gals gel and 82K # 20/40 sand. Release packer @ 5904' and RBP @ 6302'. RIH w/ 2-3/8" production tubing to 6950'. RIH w/ pump and rods. Set 456 pumping unit. Return well to production from the Blinbry/Tubb 4/5/2007.

Spud Date:

Rig Release Date:

DAC- HOB- 411

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

*Sophie Mackay*

TITLE Eng Tech

DATE 09/27/2010

\*Type or print name Sophie Mackay

E-mail address: sophie.mackay@apachecorp.com

PHONE: 918-491-4864

For State Use Only

APPROVED BY:

*[Signature]*

TITLE

PETROLEUM ENGINEER

DATE

OCT 06 2010

Conditions of Approval (if any):

ch