	, S	tate of New 1	Mexico		Form C-103	
Submit 1 Copy To Appropriate Distr District I	DE rEnergy P				October 13, 2009	
District I 1625 N French Dr., Hobbs, NM 88240 District II			WELL API NO 30-041-20			
District III 1000 Buo Brazos Rd Aztec, NM 87410 District III 1000 Buo Brazos Rd Aztec, NM 87410 OCT 00 ZUIL CONSERVATION DIVISION 1220 South St. Francis Dr.			5. Indicate Typ			
			STATE	🖾 FEE 🗌		
District IV 1220 S St. Francis Dr , Santa Fe, NM	HUBDJUCIS 4 87505	anta Fe, NM	87505	6. State Oil & 0	Gas Lease No.	
SUNDRY	NOTICES AND REPOR	RTS ON WELL	.S	7. Lease Name	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR F						
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)				PEP 36 S		
1. Type of Well: Oil Well	🛛 Gas Well 🗌	Other			2	
2. Name of Operator				9. OGRID Nun		
A1 3. Address of Operator	mstrong Energy Corpor	ation		10. Pool name	1092 or Wildcat	
	O. Box 1973, Roswell, N	IM 88202-197	3	10 ind cat Penn		
4. Well Location	·····					
Unit Letter <u>M</u>	: <u>330</u> feet fro	om the <u>South</u>	n line and	330 feet from	the <u>West</u> line	
Section 36	Township	05S	Range 33E	NMPM	<u>Roosevelt</u> County	
	11. Elevation (S	now whether D.	R, RKB, RT, GR, etc.			
12 Ch	eck Appropriate Box	r to Indicate]	Nature of Notice	Report or Othe	ar Data	
				-		
NOTICE OF INTENTI		_	SUBSEQUEN			
PERFORM REMEDIAL WOR		· <u> </u>			ALTERING CASING	
TEMPORARILY ABANDON PULL OR ALTER CASING			COMMENCE DRIL			
DOWNHOLE COMMINGLE						
OTHER:			OTHER: Per	f and acidize	\boxtimes	
13. Describe proposed or comp						
proposed work). SEE RUL	E 19.15.7.14 NMAC. For	Multiple Comple	tions: Attach wellbore	diagram of propose	d completion or recompletion.	
		35' cmt on top	of plug, PBTD @ 77	65', rd. circ hole	clean, spot 250 gals 15%	
NEFE Acid @ 7	/14′, POH,					
08-25-10 Lower Penn. RU Schlumberger, perf 7698'-7714', 2 JSPF, 120° phasing, total 32 shots, POH, RD, TIH w/ SN, 2-7/8" X 5-1/2" pkr w/ profile, on-off tool and 233 jts 2-7/8" tbg. Swabbed 101 BW, no shows.						
08-26-10 RIH, set 5-1/2" c						
08-27-10 Squeeze w/ 100 s	x Class "H" cement, sqt	ieezed @ 2900	psi, reversed 62 sx co	ement.		
Spud Date:		Rig Release I	Date:			
I hereby certify that the inform	ation above is true and c	complete to the	best of my knowledg	e and belief.		
SIGNATURE	Author		VICE PRESIDENT	<u> </u>	DATE10/04/10	
Type or print name <u>Bruce</u>	A. Stubbs E-mail ac	ldress: <u>bastu</u>	bbs@armstrongenerg	zycorp.com PH	IONE: <u>(575)</u> 625-2222	
For State Use Only		6	CTEMPI PANA	• • • • • • • • • • • •	OCT 0 6 2010	
APPROVED BY:	Kunt	TITLE	etrolgum engi	INCER I	DATE	
Conditions of Approval (if any	·):		· ···· *********			

Sales I Copy To Appropriate David Gina Sales Of NEW MICKNOW October 13, 2000 Sales I Direction Minerals and Natural Resources WELL A PI NO. October 13, 2000 Data Mark Andre, New Sector I Direction 1220 South St. Francis Dr. WELL A PI NO. October 13, 2000 Data Mark Andre, New Sector I Direction 1220 South St. Francis Dr. WELL A PI NO. October 13, 2000 Data Mark Andre, New Sector I Stands Person New York Andrew	Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103		
Fail W Aread Ave, Arten, MARLED 5 201111 CONSERVATION PUNCTOR Determined Dreamed Dreame	District I 1625 N French Dr., Hobbs, NM 3246 CEIVERSY,	Minerals and Natural Resources	WELL API NO.	October 13, 2009		
1220 \$ 8 feases 0, stants, Support Procession Deprocession of Deprocession Deprocesintend Deprocession Deprocesion Deprocession De	District II 1301 W Grand Ave Artesia NM 88210	ONSERVATION DIVISION	30-041-20940			
1220 \$ 8 feases 0, stants, Support Procession Deprocession of Deprocession Deprocesintend Deprocession Deprocesion Deprocession De	District III	220 South St. Francis Dr.				
DO NOT ISET BY DOM FOR ROPEAST TO DELIGY ON WELLS. PEP 36 STATE DO NOT ISET BY DOM FOR ROPEAST TO DELIGY ON USE DACK TO A PROPERSING TRANSFORM FOR ROPEAST TO DELIGY ON USE DACK TO A PROPERSING TRANSFORMED FOR PERMIT (COMME-101) FOR SECUT PEP 36 STATE 1. Type of Well: Oil Well © Gas Well © Other 2 2. Name of Operator 9. OGRID Number 2. Name of Operator 9. OGRID Number 3. Address of Operator 9. OGRID Number 4. Well Location 10. Pool name or Wideat 10. It letter 11. Elevation (Show whether DR. RKE, RT, GR, etc.) 11. Elevation (Show whether DR. RKE, RT, GR, etc.) 11. Elevation (Show whether DR. RKE, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON RKE, RT, GR, etc.) 13. Describe proposed completed operations. (Clearly state all pertinent datals, and give pertinent dates, including estimated date of stating any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellhore dingram of proposed completion or accompletion. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date:	District IV 1220 S St Francis Dr., Santa Fe, NMOBBSOCD	Santa Fe, NM 87505				
IDENTIFY STORM FOR PROPOSALS TO DRILLOR TO DEFERENT RESERVOR. USE "APPLICATION TOR PERMIT" (FORM C-101) FOR SUCH PEP 36 STATE PROPOSALS 1 IDENTIFY (FORM C-101) FOR SUCH PEP 36 STATE REVEALS 2 Armstrong Energy Corporation 2 1. Type of Well: Oil Well: S Gas Well C Other 9. OGRID Number 2 2. Name of Operator 9. OGRID Number 2 3. Address of Operator 9. OGRID Number 2 4. Well Location Unit Letter M.: 330 feet from the South line and 330 feet from the West line Section 36 Township 05S Range 33E NMPM Resource County II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show Whether DR, RKB, RT, GR, etc.) II. Elevation (Show whether DR, RKB, RT, GR, etc.) II. Elevation (Show Whether DR, RKB, RT, GR, etc.) II. Elevation (Show Whether DR, RKB, RT, GR, etc.) II. Elevation (Show Whether DR, RKB, RT, GR, etc.) III. Elevation (Show Whether DR, RKB, RT, GR, etc.) III. Elevation (Show Whether DR, RKB, RT, GR, etc.) III. Elevation (Show D) C HANG ASANDON (C HANG	SUNDRY NOTICES AND REP	ORTS ON WELLS	7. Lease Name or Unit	Agreement Name		
1. Type of Well: Oil Well G Gas Well Other 2 2. Name of Operator 9. OGRID Number 3. Address of Operator 9. OGRID Number 3. Address of Operator 9. OB N 1973, Roswell, NM 88202-1973 4. Well Location Do Box 1973, Roswell, NM 88202-1973 4. Well Location Mill Cat Unit Letter M. 3. Section 36 Township <oss< td=""> 8. Well Continue State State</oss<>	(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR USE "APPLICATION FOR PERI	PEP 36 STATE				
11. Option of the fight of	·					
Armstrong Energy Corporation 102 3. Address of Operator P.O. Box 1973, Roswell, NM 88202-1973 10. Pool name or Wildcat Wild Location Unit Letter M 330 feet from the South line and 330 feet from the West		Other				
P.O. Box 1973, Roswell, NM 88202-1973 Wildcat fam 4. Well Location Unit Letter M : 330 feet from the South line and 330 feet from the West line Township 05S Range 33E NMPM Roosevelt County 11. Elevation (Show whether DR. RKB, RT, GR, etc.) 11. Elevation (Show whether DR. RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK — LUG AND ABANDON CHANGE PLANS — CANNE PLUS AND ABANDON PULL OR ATTER CASING — MULTIPLE COMPL OTHER: — OTHER: POTHER: — OTHER: POTHER: — OTHER: POSCIED proposed or completed operations. (Clearly state all perilent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670°. RU Schlumberger, perf 7670°.7673°, 2 JSPF, total 7 shota, RD. TH W/ SN 2-7/8° x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661°. Spud Date: Rig Release Date: Incredy certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE		oration				
4. Well Location Unit LetterM :: 330feet from theSouthline and330feet from theWestline Section 36Township 05SRange 33ENMPMRooseveltCounty 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data SUBSEQUENT REPORT OF: REMOVED NOTO:						
Unit Letter M : 330 feet from the south line and 330 feet from the West line Section 36 Township 05S Range 33E NMPM Roosevelt County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING DUL OR ATTER CASING CHANGE PLANS COMMENCE DRILLING OPNS. P AND A DOWNHOLE COMMINGLE OTHER: Perform a cidize Z 13. Describe proposed or completed operations. (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEEE Acid at 7670°. RU Schlumberger, perf 7670°-7673°, 2 JSPF, total 7 shots, RD. TH w/ SN 2-778° x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CHBP @ 7661°. Spud Date: Rig Release Date: Three performance is true and complete to the best of my knowledge and belief. SIGNATURE TITLE Vice PRESIDENT DATE 10/04/10		I, NM 88202-1973	Wildcat ten	n		
Section 36 Township 05S Range 33E NMPM Roosevelt County 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK		from the South line and	30 feet from the	West line		
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CMMENCE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CMMENCE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON CMMENCE DRILLING OPNS. PAND A OTHER: OTHER: DOWNHOLE COMMINGLE OTHER: OTHER: OTHER: Proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TH W/SN 2-7/8''x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Thereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address:						
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING OTHER: PanD A OTHER: OTHER: Perf and acidize Image: Communication and the properties of the proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TH W/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Intereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Onty ATTE DATE<		<u> </u>				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON ALTERING CASING PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING CHANGE PLANS PAND A PULL OR ALTER CASING OTHER: PanD A OTHER: OTHER: Perf and acidize Image: Communication and the properties of the proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TH W/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Intereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Onty ATTE DATE<						
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB PAND A OTHER: OTHER: OTHER: Perf and acidize Image: Completed operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Increby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 0/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubs/s@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only TITLE PETROL BUM ENGINESH DATE OCT 0 6 2010	12. Check Appropriate B	box to Indicate Nature of Notice,	Report or Other Data	ì		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PAND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB PAND A OTHER: OTHER: OTHER: Perf and acidize Image: Completed operations. Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Increby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 0/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubs/s@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only TITLE PETROL BUM ENGINESH DATE OCT 0 6 2010						
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB P AND A OTHER: OTHER: OTHER: OTHER: MULTIPLE COMPL CASING/CEMENT JOB 13. Describe proposed or completed operations. (Clearly state all perinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8'' x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: Intereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE10/04/10_ Type or print name Bruce A. Stubbs E-mail address:bastubbs/@armstrongenergycorp.com PHONE: (\$75) 625-2222 For State Use Only TITLE PETROL BUM PINORESH DATEOCT 0 6 2010						
DOWNHOLE COMMINGLE OTHER: OTHER: Perf and acidize Image: Completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only TITLE PETROL BUM ENGINEERING DATE OCT 0 6 2010						
OTHER: OTHER: Perf and acidize Image: Construct of the second seco		COMPL 🗌 CASING/CEMENT	JOB 🗌			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8'' x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEER QCT 0 6 2010						
proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion. 08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEER DATE QCT 0 6 2010	OTHER:	OTHER: Per	f and acidize	\square		
08-30-10 Mid Penn. Circ hole clean, spot 250 gals 15% NEFE Acid at 7670'. RU Schlumberger, perf 7670'-7673', 2 JSPF, total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEER: DATE OCT 0 6 2010						
total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE B. M. M. TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEER DATE OCT 0 6 2010	proposed work). SEE RULE 19.15.7.14 NMAC. F	or Multiple Completions: Attach wellbore	diagram of proposed compl	etion or recompletion.		
total 7 shots, RD. TIH w/ SN 2-7/8" x 5-1/2 pkr w/ profile, on-off tool, and 232 jts tbg, show of gas. 09-20-10 Set CIBP @ 7661'. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE B. M. M. TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEE DATE OCT 0 APPROVED BY: TITLE	08-30-10 Mid Penn. Circ hole clean, spot 250 g	als 15% NEFE Acid at 7670'. RU Schl	umberger, perf 7670'-76	73', 2 JSPF,		
Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE B. M. TITLE VICE PRESIDENT DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PETROLEUM ENGINEER DATE OCT 0 OCT 0 OCT 0 TITLE DATE				, ,		
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER APPROVED BY: DATE	09-20-10 Set CIBP @ 7661'.					
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER APPROVED BY: DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER APPROVED BY: DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER APPROVED BY: DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE TITLE DATE DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE TITLE DATE DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE TITLE DATE DATE						
I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNATURE SIGNATURE DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE TITLE DATE DATE	Spud Date:	Rig Release Date:				
SIGNATURE Batter DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE DATE DATE OCT 0 6 2010						
SIGNATURE Batter DATE 10/04/10 Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010 TITLE DATE DATE OCT 0 6 2010	I hereby certify that the information above is true an	d complete to the best of my knowledge	e and helief	* 78		
Type or print name Bruce A. Stubbs E-mail address: bastubbs@armstrongenergycorp.com PHONE: (575) 625-2222 For State Use Only PETROLEUM ENGINEER DATE OCT 0 6 2010	R AL					
For State Use Only PETROLEUM ENGINEER APPROVED BY: DATE	SIGNATURE Deffutur	TITLE VICE PRESIDENT	DATE	10/04/10		
APPROVED BY:	Type or print name <u>Bruce A. Stubbs</u> E-mail	address: <u>bastubbs@armstrongenerg</u>	ycorp.com PHONE:	(575) 625-2222		
APPROVED BY:						
	13 All -1	PETROLOUM ENVIRON		OCT 0 6 20 10		
	Conditions of Approval (if any):	, X I X IJJ <u></u>				

Submit 1 Copy To Appropriate District Office	State of New Mexico	Form C-103		
District I	Energy, Minerals and Natural Resources	October 13, 2009		
1625 N French Dr Hobbs NM 88240		WELL API NO.		
	CONSERVATION DIVISION	30-041-20940		
1301 W. Grand Ave , Artesia, NV 85210	BE CONSERVATION DIVISION	5. Indicate Type of Lease		
		STATE S FEE		
District IV OCT 052	U10 Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S St Francis Dr, Santa Fe, NM 87505	nC.D			
SUNDRANDDRES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS	TO DRILL OR TO DEEPEN OR PLUG BACK TO A			
DIFFERENT RESERVOIR. USE "APPLICATIO	ON FOR PERMIT" (FORM C-101) FOR SUCH	PEP 36 STATE		
PROPOSALS)		8. Well Number		
1. Type of Well: Oil Well 🛛 Gas	Well 🔲 Other	2		
2. Name of Operator		9. OGRID Number		
1	nergy Corporation	1092		
3. Address of Operator	•••	10. Pool name or Wildcat		
P.O. Box 197	Wildcat Penn			
4. Well Location				
Unit Letter <u>M</u> : <u>33</u>	0 feet from the <u>South</u> line and	330 feet from the <u>West</u> line		
Section 36	Township 05S Range 33E	NMPM Roosevelt County		
11	. Elevation (Show whether DR, RKB, RT, GR, etc.			
12 Check Appr	conrigte Box to Indicate Nature of Notice	Report or Other Data		

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:				SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK		PLUG AND ABANDON		REMEDIAL W	ORK		ALTERING CASING	; 🗌
TEMPORARILY ABANDON		CHANGE PLANS		COMMENCE	DRILLING OPNS.		P AND A	
PULL OR ALTER CASING		MULTIPLE COMPL		CASING/CEM	ENT JOB			
DOWNHOLE COMMINGLE								
0711ED				OTUED.				57
OTHER:				OTHER:	Perf and acidize			

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Upper Penn. Perf 7647.5'-7651', 14 shots, broke down w/ 250 gals 15% NEFE Acid. Swabbed, back load, testing. 09-21-10

Spud Date:		Rig Releas	se Date:		
I hereby certify	y that the information above	is true and complete to t	he best of my knowledge and bel	ief.	
SIGNATURE	2 Mil	LITLE	VICE PRESIDENT	DATE_	10/04/10
Type or print r	nameBruce A. Stubbs	E-mail address:ba	stubbs@armstrongenergycorp.cc	m PHONE:	_(575) 625-2222
For State Use APPROVED I Conditions of		TITLE_	PETROLEUM ENGINEER	DATE_	OCT 0 6 2010.