Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS

SEP 28 2010 HORRSOCD FORM APROVED 007

	OMB NO. 1004-013		
	EXPIRES: March 31, 20		
5.	Lease Serial No		

Do not use this for	m for proposals to drill or to re-enter an HOBBSOC	NM - 98189	
	se Form 3160-3 (APD) for such proposals	6. If Indian, Allottee or Tribe Name	
SI	UBMIT IN TRIPLICATE		
		7. Unit or CA Agreement Name and No.	
1a. Type of Well Oll Well Ga	as Well Other		
	8 Well Name and No.		
2. Name of Operator	Nana 30 Fed 1H		
DEVON ENERGY PRODUC	9. API Well No.		
3. Address and Telephone No.	30-025-39365		
20 North Broadway, Oklahor	10. Field and Pool, or Exploratory		
4. Location of Well (Report location clear	Lusk North; Bone Spring		
L: 2310' FSL 660' FEL Unit I Sec 30	11. County or Parish State		
 BHL: 358' FSL & 677' FEL	Lea NM		
	CK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTIC	E. REPORT, OR OTHER DATA	
TYPE OS SUBMISSION	TYPE OF	ACTION	
Notice of Intent	Alter Casing Fracture Treat	Production (Start/Resume) Reclamation Water Shut-Off Well Integrity	
✓ Subsequent Report		Recomplete	
Final Abandonment Notice	Convert to Injection Plug Back	Temporarily Abandon Water Disposal	
13 . Describe Proposed or Completed Operations (C	learly state all pertinent details, and give pertinent dates, including estimated date of ubsurface location and measured and true vertical depths of all pertinent markers and	starting any proposed work and approximate duration thereof If the proposal	
Rond No. on file with BLM/BIA. Required subsequent	reports shall be filed within 30 days following completion of the involved operations	If the operation results in a multiple completion or recompletion in a new interval, a	
Form 3160-4 shall be filed once testing has been com	pleted Final Abandonment Notices shall be filed only after all requirement, including	reclamation, have been completed, and the operator has determined that the site	
ready for final inspection)			
TIOTHO TIONAL MIDH DIL DT @ 4	500#. TAG tbg @ 4992'. Drill out DV tool @ 4889'. PT csg @ 150	20# BILL without a 2nd DV tool TAG @ 7255	
Drill out DV tool & CHC. PT csg		10# Kill Wilby to Zild DV tool TAO @ 1233.	
	og dress DV tool @ 4990' & 7255'. TAG @ 9683'. CMT to PBTD	@ 9715'	
8/2/10: RU BJ PT lines @ 3000#. Pum	p 25 BBLS gel sweep. Displace w/214 BBLS 2% KCL. 10% Acel	ic Acid. FL w/44.9 BBLS KCL	
8/3/10: Perf Bone Springs @ 9695'-97', 9495'-97, 9295'-97' (6SPF) 36 Holes. Pump 5 BBLS 2% KCL. ND BOP NU FRAC Valve. RD BJ			
8/4/10: RU BJ WL & Stinger. Pump 47.6 BBLS 7.5% HCL, 47.6 BBLS 10# Linear Gel, 4108 BBLS Spectra Star			
	199545# 20/40 white SD, tall w/63844# 20/40 Super LC. FL w/2		
CBP @ 9170'. Perf @ 9045'-47', 8845'-47' (6SPF) 36 Holes. RD WL. Drop Frac Ball. RU BJ			
	@ 3557#. Pump 2000 gal 7.5% HCL, 4354 BBLS Spectra Star 2		
f .	Super LC, FL w/200 BBLS 10# Linear Gel, RD BJ.		

14. I hereby certify that the foregoing is true and corr

Name Title

8/6/10: ND Frac Valve, NU BOP. RIH w/Bit & tbg TAG @ 9166', Clean out SD, drill out CBP. RIH w/tbg TAG bottom of CBP @ 9683'. RIH

8/9/10: RIH w/ tbg TAG @ 9715'. RIH w/Prod tbg 2 7/8" N-80. ND BOP Set TAC NU WH. TAC @ 7226', NU @ 7290', EOT @ 8250'

Spence Laird Regulatory Analyst

Date

9/9/2010

(This space for Federal or State Office use)

1500 N 1906 E

w/tbg to PB @ 9715', CHC.

8/10/10 - 8/11/10: RIH w/Pump. HWO RD PU. TOP

Approved by

Signed

Conditions of approval, if any:

Title

Date

its junsdiction

*See Instruction on Reverse Side

SEP_ 2 7 2010

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE

Notice State A 4 min 5 .