

Bill Richardson
Governor

Jim Noel
Cabinet Secretary
Karen W. Garcia
Deputy Cabinet Secretary

Mark Fesmire
Division Director
Oil Conservation Division



Response Required – Deadline Enclosed

*Underground Injection Control Program
"Protecting Our Underground Sources of Drinking Water"*

19-Oct-10

LEGACY RESERVES OPERATING, LP
P. O. BOX 10848
MIDLAND TX 79702-

**LETTER OF VIOLATION and SHUT-IN DIRECTIVE
Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

SOUTH JUSTIS UNIT No.212

Active Injection - (All Types)

30-025-31804-00-00
L-24-25S-37E

Test Date: 10/14/2010	Permitted Injection PSI:	Actual PSI:
Test Reason: Annual IMIT	Test Result: F	Repair Due: 1/17/2011
Test Type: Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT: WELL WOULD NOT HOLD PRESSURE DURING TEST*****OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****		

SOUTH JUSTIS UNIT No.232

Active Injection - (All Types)

30-025-31864-00-00
A-26-25S-37E

Test Date: 10/14/2010	Permitted Injection PSI:	Actual PSI:
Test Reason: Annual IMIT	Test Result: F	Repair Due: 1/17/2011
Test Type: Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:
Comments on MIT: ****WOULD NOT HOLD PRESSURE ***FAILED PRESSURE TEST***OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****		



SOUTH JUSTIS UNIT No.202

30-025-31967-00-00
G-23-25S-37E

Active Injection - (All Types)

Test Date: 10/14/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 1/17/2011
Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: ****WOULD NOT HOLD PRESSURE DURING PRESSURE TEST****OPERATOR IN VIOLATION OF
NMOCD RULE 19.15.26.11*****

SOUTH JUSTIS UNIT No.180

30-025-32241-00-00
O-13-25S-37E

Active Injection - (All Types)

Test Date: 10/14/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 1/17/2011
Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: *****PRESSURED UP TWICE WELL WOULD NOT HOLD PRESSURE-FAILED PRESSURE
TEST****OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11*****

SOUTH JUSTIS UNIT No.280

30-025-32408-00-00
H-36-25S-37E

Active Injection - (All Types)

Test Date: 10/15/2010 Permitted Injection PSI: Actual PSI:
Test Reason: Annual IMIT Test Result: F Repair Due: 1/18/2011
Test Type: Std. Annulus Pres. Test FAIL TYPE: Other Internal Failure FAIL CAUSE:
Comments on MIT: *****WOULD NOT HOLD PRESSURE DURING PT; TRUCKDRIVER HAD TO RELOAD BACKSIDE
DURING 2 ATTEMPTS****FAILED PT****OPERATOR IN VIOLATION OF NMOCD RULE
19.15.26.11*****

In the event that a satisfactory response is not received to this letter of direction by the "Repair Due:" date shown above, or if the well(s) are not immediately shut-in, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely,




Hobbs OCD District Office

COMPLIANCE OFFICER

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



015H14150977
\$0.44
10/19/10
Mailed From 88240

US POSTAGE

LEGACY RESERVES OPERATING LP
P.O. BOX 10848
MIDLAND, TX 79702