Inew Maiga Opp Gorasio Davisias Form 3160-5 (April 2004) UNITED STAT 30 Hobbs, French Provenu UNITED STAT 30 Hobbs, FM 88240210 DEPARTMENT OF THE ANDER SA 20210 BUREAU OF LAND MANAGEMENT SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well Gas Well Other 2. Name of Operator P.O. BOX 1592, ROSWELL, NM 88202-1592 3b. Phone No. (include area code) 575-623-9799 575-623-9799 4. Location of Well (Footage, Sec., T., R., M. or Survey Description) 4. 4. 4.				FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007 5. Lease Serial No. NMNM103880 6. If Indian, Allottee or Tribe Name 7. If Unit or CA/Agreement, Name and/or No. 8. Well Name and No. Cedar Point 14-L Federal No. 1 9. API Well No. 30-005-29153 10. Field and Pool, or Exploratory Area	
1980' FSL & 660' FWL, SECTION 14, T15S, R30E, NMPM			11. County or Parish, State		h, State /
				Chaves County, New Mexico	
12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA_					
TYPE OF SUBMISSION	TYPE OF ACTION				
Notice of Intent Acidize Deepen Production (Start/Resume) Water Shut-Off Subsequent Report Casing Repair New Construction Recomplete Well Integrity Final Abandonment Notice Convert to Injection Plug and Abandon Temporarily Abandon BOP test 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) SPUD WELL @ 1:30 PM ON 9/7/10. DRLD 17.5" HOLE TO 630'. CIRC HOLE IN PREP TO RUN CSG. RUN 14 JTS 13 3/8" 48# CSG TO 626'. CMTD W/650 SX "C" + 2% CaCl. CIRC 222 SX TO SURFACE. WOC AND CLEAN PITS. CUT OFF CONDUCTOR AND CSG. WELD ON CSG HEAD. NU BOP AND CHOKE MANIFOLD. TEST BOP AND MANIFOLD - LOW 200 PSI, HIGH 1400 PSI, ALL TESTED OK.					
		•		KE(
	OCT 2520			001	052010
HOBBSOCD NMOCD ARTESIA					
14. I hereby certify that the foreg Name (Printed/Typed)					
			RODUCTION ANAL	YST	
Signature anet D. Torpal Date				09/09/2010	
ACCEPTED FOR THIS SEACE FOR FEDERAL OR STATE OFFICE USE					
Approved by DAVID Conditions of approved pif any, are a certify that the applicant holds legal which would entitle the applicant to	conduct operations thereon.	loes not warrant or the subject lease Of	fik26 - 10	Date	
Title 18 U.S.C. Section (101) and Title States any falser fictulity of Fruching	45-U.S.C. Section 1212, make it a fit statements or representations a GINE R		owingly and willfully to jurisdiction.	make to any departr	nent or agency of the United
(Instructions on page 2)	·	1)			1

2

1

/