

Submit 1 Copy To Appropriate District  
Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Hobbs, NM 88240  
District III  
1000 Rio Pecos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM  
87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
October 13, 2009

**RECEIVED**  
NOV 02 2010  
HOBBS CO

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30-025-29533
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. VO-6545 E-2013-1
7. Lease Name or Unit Agreement Name South Four Lakes Unit
8. Well Number 008
9. OGRID Number 151323
10. Pool name or Wildcat <del>Four Lakes</del> SWD Devonian

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input checked="" type="checkbox"/> Other <input type="checkbox"/> SWD	
2. Name of Operator Pride Energy Company	
3. Address of Operator PO Box 701950 Tulsa, OK 74170-1950	
4. Well Location Unit Letter A : 660 feet from the North line and 990 feet from the East line Section 2 Township 12S Range 34E NMPM Lea County	
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4148' GR, 4171' KB	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: perform MIT <input checked="" type="checkbox"/>		OTHER: <input type="checkbox"/>	

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Intend to do the following:

1. Rig up pulling unit & POOH with 3 1/2" tubing
2. Fix hole in tubing
3. Test tubing up to 5,000 psi
4. Run tubing in hole & set packer at 9829' (top perf at 9902')
5. A Mechanical Integrity Test (MIT) will be performed and a chart will be recorded.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Matthew L. Pride TITLE By: Pride Production Co., Inc.  
Matthew L. Pride Title: General Partner  
By: Matthew L. Pride DATE 10/8/10  
Title: President  
Type or print name Matthew L. Pride E-mail address: Mattp@pride-energy.com PHONE: (918) 524-9200

For State Use Only

APPROVED BY: [Signature] TITLE Staff MGR DATE 11-2-10  
Conditions of Approval (if any):