Submit 3 Copies To Appropriate District Office	State of New Mexico	Form C-103
Office District I 1625 N. French Dr., Hobbs, NM 88240 ECEV District II	y, Minerals and Natural Resources	WELL API NO.
1201 W. C I	CONSERVATION DIVISION	30-025-02203 5. Indicate Type of Lease
District III NUV U 1 7(1)11	1220 South St. Francis Dr.	STATE FEE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM BBSOCI	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
87303		B-1406
SUNDRY NOTICES AND (DO NOT USE THIS FORM FOR PROPOSALS TO DRI	LL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PROPOSALS.)	PERMIT" (FORM C-101) FOR SUCH	West Vacuum Unit
1. Type of Well:		8. Well Number
Oil Well Gas Well Other		9. OGRID Number
2. Name of Operator Chevron USA, Inc.	/	4323
3. Address of Operator	Tv 70705	10. Pool name or Wildcat Vacuum; Grayburg San Andres
#15 Smith Rd., Midland	, 1 x 7 9 7 0 5	vacuum, Grayburg San Andres
Unit Letter W : 1980 feet from the North line and 660 feet from the East line		
	Township 17-S Range 34-E	NMPM Lea County
	tion (Show whether DR, RKB, RT, GR	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)		
Pit Location: UL H Sect 34 Twp 17S Rng 34E Pit type Steel Depth to Groundwater Distance from nearest fresh water well Over 1000'		
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng;		
1980 feet from the North line and 660 feet from the East line		
	te Box to Indicate Nature of No	tice, Report or Other Data
NOTICE OF INTENTIO PERFORM REMEDIAL WORK ☐ PLUG AN		SUBSEQUENT REPORT OF: WORK ALTERING CASING
PERFORM REMEDIAL WORK PLUG AI		_
TEMPORARILY ABANDON	PLANS COMMENC	E DRILLING OPNS.□ PLUG AND □ ABANDONMENT
PULL OR ALTER CASING MULTIPL		ST AND
COMPLE	TION CEMENT JO	DR
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion		
or recompletion.	:	s. Attach Helicole diagram of proposed completion
1. 10/18/10 Notified OCD on MIRU to P&A 2. 10/19/10 Tag CIBP@4313' Spot 25sx C Cmt F/4:		. 10/22/10 Perf & SQZ'd 75sx C Cmt@60' (Fr. Wtr./Surf) Circ to Surf WOC Tagged@Surf
3. 10/19/10 Displace hole w/MLF 9.5# Brine w/25# 4. 10/20/10 Perf & SQZ'd 50sx C Cmt@2800' (B. Sc	Gel P/BBL 8.	10/22/10 Install Dry Hole Marker
5. 10/21/10 Perf & SQZ'd 65sx C Cmt1680' (Shoe/	Γ. Salt) WOC Tagged@1400'	Approved for plugging of well bore only. Liability under bond is retained pending receipt
6. 10/21/10 Perf & SQZ'd 105sx C Cmt@400' (Fr W Tagged@125' 10/22/10	tr/ Sun) WOC	of C-103 (Subsequent Report of Well Plugging) which may be found at OCD Web Page under
I hereby certify that the information above is true and complete to the best of my knowledge and relief, whith the information above is true and complete to the best of my knowledge and relief, whith the constructed or closed according to NMOCD guidelines , a general permit or an attached alternative OCD-approved plan.		
SIGNATURE	TITLE MANAGE	DATE 10/25/10
Type or print name Jimmy BAGLEY E-mail address: sunsetwellservice@yahoo.com Telephone No. 432-561-8600		
(This space for State use)		
APPPROVED BY	TITLE THAT	- MAR DATE / 1-2-10
Conditions of approval, if any:		

d/