Submit 1 Copý To Appropriate District Office	State of New Mexico	Form C-103
District I	Energy, Minerals and Natural Resources	October 13, 2009
District II		WELL API NO. 30-025-01269
1301 W. Grand Ave., Artesia, NM 88210	Energy, Minerals and Natural Resources OIL CONSERVATION DIVISION 1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NW-87410 / LUI	0	STATE FEE
District IV 1220 S. St. Francis Dr., Santal OBBSOC 87505	Santa Fe, NM 8/303	6. State Oil & Gas Lease No.
SUNDRY NOTICES	S AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATIVE PROPERTY OF THE PROPERTY	S TO DRILL OR TO DEEPEN OR PLUG BACK TO A ON FOR PERMIT" (FORM C-101) FOR SUCH	NEW MEXICO "A"
PROPOSALS.)	Well M Other SWD	8. Well Number # 002
2. Name of Operator		9. OGRID Number 253010
KENEMORE WELDING & OILFIELI  3. Address of Operator	D SERVICES, INC.	
PO BOX 154, MALJAMAR, NM 8826	54	10. Pool name or Wildcat SWD; PERMO UPPER PENN
4. Well Location		
	61 feet from the <u>SOUTH</u> line and	1983 feet from the <u>EAST</u> line
Section Q5	Township 16s Range 33E	NMPM LEA County
	. Elevation (Show whether DR, RKB, RT, GR, etc.)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
	- <del> </del>	_
NOTICE OF INTE	NTION TO: SUB: LUG AND ABANDON ☐ REMEDIAL WORI	SEQUENT REPORT OF:
	HANGE PLANS COMMENCE DRI	
	ULTIPLE COMPL	
DOWNHOLE COMMINGLE		_
OTHER: PACKING & TUBING REPLAC	EMENT NOTHER:	and the second second
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
NOTIFY NM OCD MAXEY BROWN OF PENDING WORK 10/26/10. INTED TO PULL PACKER & PIPE, DRILL OUT OLD		
PAKER, CLEAN OUT HOLE TO BOTT	FOM. RUN NEW PACKER & TEST PIPE BACK	I PACKER & PIPE, DRILL OUT OLD IN & PRESSURE TEST & DO ACID JOB.
Per Underground Injection Control Progr	ram Manual Condition of A	pproval : Notify OCD Hobbs
II.6.c. Packer shall be set within or less to of the uppermost injection perfs or open	then 100 feet office 24 hou	rs prior to running MIT Test & Chart
of the appennost injection pens of open		
	office 24 hours	pproval: Notify OCD Hobbs s prior to running MIT Test & Chart
. حوالت المستد	Rig Release Date:	Chart
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Junge Kenemo TITLE PRESIDENT DATE 10/26/10		
Type or print name GEORGE KENEMORE E-mail address: gkenemore@leaco.net PHONE: 575-390-6951		
APPROVED BY:	TITLE START ME	DATE 11-2-10
Condition of Approval: Notify OCD Hobbs office 24 hours prior to running MIT Test & Chart.		



