Submit 1 Copy To Appropriate District Office <u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	State of New Mexico Minerals and Natural Resources	Form C-103 October 13, 2009 WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 NOV 10 District III 1000 Rio Brazos Rd., Aztec, NM 8741 HOBBS District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	VIL CONSERVATION DIVISION	30-025-26677 5. Indicate Type of Lease STATE X FEE 6. State Oil & Gas Lease No.
SUNDRY NOTICES AN (DO NOT USE THIS FORM FOR PROPOSALS TO DIFFERENT RESERVOIR. USE "APPLICATION F		7. Lease Name or Unit Agreement Name East Vacuum GSA Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas We	II X Other Injection	8. Well Number 6
2. Name of Operator ConocoPhillips Com		9. OGRID Number 217817
3. Address of Operator 3300 N "A" St Bld Midland, TX 7970.		10. Pool name or Wildcat Maljamar; Grayburg-San Andres
4. Well Location		
Unit Letter F : 1450 feet from the North line and 2500 feet from the West line		
Section 32	Township 17S Range 35E evation (Show whether DR, RKB, RT, GR, etc.)	NMPM CountyLea
	S'GL	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
TEMPORARILY ABANDON	ION TO: SUB AND ABANDON REMEDIAL WOR GE PLANS COMMENCE DRI IPLE COMPL CASING/CEMENT	LLING OPNS. P AND A
	E RULE 19.15.7.14 NMAC. For Multiple Con	d give pertinent dates, including estimated date npletions: Attach wellbore diagram of
tubing followed by 4 bbls brine, install hy 10/7/2010 rig up tuboscope, 22 bad jts, pi packer at 2081' 10/8/2010 continue with scraper and work 10/11/2010 unset packer, trip in with brid from 4281' to surface, held 10/12/2010 unset packer and circ with 10: 4673, cleaning of fill down to 4755', circ v 10/14/2010 unset packer and trip out with npop, 133 jts 2 7/8" douline 10/15/2010 circ 120 bbls packer fluid, late held for 30 min. install flow line on tree, I	ew down well 4 hrs, pump 40 bbls of brine. Purdril dril ick up 5 1/2" casing scraper, 14 jts, packer and kstring, tag fill at 4660', had 95' of fill. pull scr ge plug and packer to test 5.5" casing, set brid # brine, trip out with packer and plug, trip in w well clean, packer set at 2500' workstring, trip back with pump out plug, pac ch back on the on/off tool nipple, down BOP,	workstring, ran scraper down to 2522', set aper up to 4317', set packer at 3876' ge plug at 4286' and packer at 4281', pressure with 4.75" bit, 6 ea collars and tubing, tag up at ker, npod/pcid, xl on/off with 1.875 F profile
Spud Date: Chart attached	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
	and complete to the best of my knowledge	e and bener.
SIGNATURE B= JM:	TITLE Regulatory Specialist	DATE_11/08/1981
Type or print name Brian D Maiorino	E-mail address: brian.d.maiorino	@conocophillipsRtatenNE: (432)688-6913
For State Use Only APPROVED BY: Conditions of Approval (if any):	TITLE STRIGT 1 SUPERVI	NOV 1 2 2010

