Submit I Copy To Appropriate District Office	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Polarito Sources	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-025-07302
District III	1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE X
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM		
87505 SUNDRY NOTICES	AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		H, V. Black
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		
1. Type of Well: Oil Well 🔀 Gas Well 🗌 Other		8. Well Number 1
2. Name of Operator Celero Energy II, LP		9. OGRID Number 247128
3. Address of Operator 400 W. Illinois, Ste. 1601		10. Pool name or Wildcat
Midland, TX /	9701	South Knowles (Devonian)
4. Well Location		
Unit Letter_K : 1980 feet from the South line and 1980 feet from the West line Section 13 Township 17S Range 38E NMPM CountyLea		
Section 13	Township 17S Range 38E . Elevation (Show whether DR, RKB, RT, GR, etc	
[11] A. S. Line and M. S.		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO:		
TEMPORARILY ABANDON	HANGE PLANS	
	JLTIPLE COMPL	ЛТ ЈОВ
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date		
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
 R1H with workstring to 12100', Spot balanced cement plug of 25 sx Class H and tag, 		
3) Circulate hole with 10 ppg salt mud,		
4) Spot the following cement plugs while pulling out of hole:		
9000', 25 sx Class H, <u>6000', 25 sx Class C</u> > Reaf \$59 35 sx cmt - @ 4855' - woc/rag 3000' 25 sx Class C		
Sout, 20 bh Onice C,		
400-surface, 40 sx Class C. 5) Remove wellhead, set P&A marker, clean and remediate location.		
	The Oil Cons	servation Division Must be notified
Spud Date:	Rig Release Da 24 hours pr	ior to the beginning of plugging operations.
	· _ · _ · _ · _ · _ · _ · · · ·	
I have be appetitive that the information above	ve is true and complete to the best of my knowled	la and ballef
Thereby certify that the information above	ve is the and complete to the best of my knowled	ige and benef.
SIGNATURE AWA THU	TITLE Regulatory Analyst	DATE_11/29/2010
Type or print name Lisa Hunt	E-mail address: <u>lhunt@celeroer</u>	ergy.com PHONE: (432)686-1883 /57
For State Use Only		
5/00/ / / / / / / / / / / / / / / / / /		
APPROVED BY DATE / Conditions of Approval (if any):		
Conditions of Approval (Faily).		



H . V. Black #1 - 1980' FSL & 1980' FWL OF Sec 13, T-17S, R38E - UL "K" API No: 30-025-07302



H . V. Black #1 - 1980' FSL & 1980' FWL OF Sec 13, T-17S, R38E - UL "K" API No: 30-025-07302