Form C-101 June 16, 2008

1625 N. French Dr., Hobbs, NM 88240

FOR Phergy Minerals and Natural Resources

District II 1301 W. Grand Avenue, Artesia, NM 88210

1000 Rio Brazos Road, Aztec, NM 8741 JUL 30 2010

District IV 1220 S. St. Francis Dr., Santa Fe, NM BOBBSOCD Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit to appropriate District Office

☐ AMENDED REPORT

DE ENTED DEEDEN

PLUGBA				A ZONE	J DKII	ul, N	CC-CIN	IEK,	DEE	ren,				
Operator Name and Address SandRidge E&P, LLC								² OGRID Number 270265						
				123 Robert S Kerr Ave OKC OK 73102-6406						³ API Number 30 – 025-32925				
³ Property Code 309607			/	⁵ Property Name Caprock Maljamar Un					t		⁶ Well No. 149			
	Pea	!(*	Proposed Pool 1 Queen	•				¹⁰ Proposed Pool 2						
['] Surface I	_ocatio	n												
UL or lot no. K				Range 33E	Lot Idn		Feet fro		North/South line S		Feet from the 2685	East/	West line W	County
⁸ Proposed B	⁸ Proposed Bottom Hole Location If Different From Surface													
UL or lot no. Section			Township Range				Feet fro	om the	North/South line		Feet from the East/West line		West line	County
Additional	Well	Info	rmat	ion				٠						
Work Type Code				¹² Well Type Co O	13 Cable/Rotary R			¹⁴ Lease Type Code State		¹⁵ Ground Level Elevation 4223				
16 Mul		¹⁷ Proposed Depth 4950			¹⁸ Formation Queen				¹⁹ Contractor			²⁰ Spud Date 06/30/10		
²¹ Propose	d Casii	ng ai	nd C	ement Prog	ram		·							
Hole Size		Casing Size						5	Setting Depth Sa		Sacks of Ce	Sacks of Cement		Estimated TOC

ON FII	LE													
NO CHAI	NGE													

Well was originally completed in the Maljamar; Grayburg-San Andres. It is proposed to add the Queen formation and downhole commingle as per Attached procedure.

Yates, Seven Rivers, Queen not part of Caprock Maljamar Unit. Operator will have to rename property to produce from these zones.

Permit Expires 2 Years From Approval Date Unless Drawing Underwa

OCD CONDITION OF APPROVAL of Drilling: Intent to drill ONLY --- CANNOT produce until the Non-Standard Location has been approved by OCD Santa Fe office.

²³ I hereby certify that the information given above is true and complete to the best of my knowledge and belief.	OIL CONSERVATION DIVISION						
Signature: Serri Stathemy	Approved by:						
Printed name: Terri Stathem	Title: PETROLEUM ENGINEER						
Title: Regulatory Manager	Approval Date: DEC 0 1 2010 Expiration Date:						
E-mail Address: tdstathem@sdrge.com	Oil Conservation Division						
Date: 7/27/10 Phone: 405-429-5500	Conditions of approval: Approval for drilling/workover ONLY— CANNOT produce Downhole Commingled until						
	DHC is approved in Santa Fe.						

²² Describe the proposed program. If this application is to DEEPEN or PLUG BACK, give the data on the present productive zone and proposed new productive zone. Describe the blowout prevention program, if any. Use additional sheets if necessary.

RECEIVED

JUL 30 2019

State of New Mexico

Form C-102

1625 N. French Dr., Hobbs, NM 88240 OBBSOCEDY, Minerals & Natural Resources Department District II

Revised July 16, 2010 Submit one copy to appropriate

1301 W. Grand Avenue, Artesia, NM 88210

OIL CONSERVATION DIVISION

District Office

District III

1000 Rio Brazos Rd., Aztec, NM 87410

1220 South St. Francis Dr. Santa Fe, NM 87505

☐ AMENDED REPORT

District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

· · · · · ·		W	ELL LC	CATIO)	N AND ACE	REAGE DEDIC	ATION PLA	T		
1	API Numbe	r		² Pool Code		³ Pool Name				
30	-025-329	25	L	4997D PORTSOLL Wildrent; Queen						
Property Code				6,	6 Well Number					
1457	8			149						
OGRID No.			, , , , , , , , , , , , , , , , , , , 		9 Elevation					
270265				4223						
					¹⁰ Surface	Location				
UL or lot no.	Section	Township	Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
K	18	178	33E		1339	South	2685	West	Lea	
			II Bo	ttom Ho	le Location I	f Different Fron	n Surface	:		
L or lot no.	L or lot no. Section Town		Range	Lot Idn	Feet from the	North/South line	Feet from the	East/West line	County	
² Dedicated Acre	s ¹³ Joint o	r Infill 14 C	onsolidation (Code 15 Or	der No.					
40 .	}	1		- 1	А	154-35	104			

No allowable will be assigned to this completion until all interests have been consolidated or a non-standard unit has been approved by the division.

Commence of the second			
			17 OPERATOR CERTIFICATION I hereby certify that the information contained herein is true and complete
			to the best of my knowledge and belief, and that this organization either
			ดพาเร a working interest or unleased mineral interest in the land including
			the proposed bottom hole location or has a right to drill this well at this
			location pursuant to a contract with an owner of such a mineral or working
			interest, or to a voluntary pooling agreement or a compulsory pooling
			order heretofore entered by the division.
			Danis W. Tally 723/10 Signature Date
	•		Donald W. Tally, Jr. Printed Name
			dtally@sdrge.com E-mail Address
			1801 IDAMENOD GEDTHEIGA TON
			¹⁸ SURVEYOR CERTIFICATION
│			I hereby certify that the well location shown on this
2707.6		•	plat was plotted from field notes of actual surveys
			made by me or under my supervision, and that the
			same is true and correct to the best of my belief.
Z685' E	21.5',	•	2/23/1995
			Date of Survey
			Signature and Seal of Professional Surveyor.
		İ	
M			
m m			P. R. Patton - 8112
			Certificate Number
			·



K-17-175-33E

SandRidge Tertiary, LLC

6 Desta Drive, Suite 6300 • Midland, TX 79705 • Phone 432.687.4242 • Fax 432.687.4244 • sandridgenergy.com

Caprock Maljamar Unit #149 API # 30-025-32925

Clean out and Acidize Current Perforations - Add Perfs in Queen/Seven Rvrs / Yates

Procedure

Procedure:

- 1) Hot water well 48 hrs before rigging up.
- 2) Test Anchors.
- 3) MIRU Well Service Unit.
- 4) Pull rods and pump.
- 5) ND Wellhead and NU BOP.
- 6) Release TAC and pull tubing.
- 7) PU bit sub & 4 3/4" bit on tubing
- 8) Run in and tag up. PBTD is 4480'.
- 9) If necessary, MIRU Reverse Unit and proceed. If no clean out needed, skip to step #16.
- 10) PU 4 3/4" bit on 6 3 1/4" drill collars on tubing.
- 11) RIH to top of fill.
- 12) Break circulation and drill / circulate hole clean to 4480
- 13) At +/- 4480 circulate until water cleans up.
- 14) Pull tubing and laydown tools.
- 15) RDMO Reverse Unit.
- 16) Pick up RBP & Treating Packer on tubing.
- 17) Hydro Test tubing in hole.
- 18) RIH & set RBP @ 4400'
- 19) Pull up land packer @ +/-4150'

CMU #149 ADD QUEEN-7R-YATES PROCEDURE.DOC

- 20) RU Acid company with 2000 gallons 15% NEFE Anti-Sludge HCl acid containing H2S scavenger for 5000 ppm H2S + 1% by volume mutual solvent. Have 1200# graded rock salt and 10# brine on location for diversion.
- 21) Spot acid to packer and set packer.
- 22) Acidize perfs 4203-4371 in 4 equal stages using graded rock salt for diversion.
- 23) Flow back until well dies
- 24) Swab back load.
- 25) Release packer.
- 26) RIH washing salt if necessary to retrieve RBP.
- 27) Latch and release RBP.
- 28) Pull and set RBP @ 3800'
- 29) Pull and LD packer.
- 30) Rig up wireline company and Perforate Queen (2 JSPF) 3635 3659 (49 holes).

Reference Log - Halliburton Dual Spaced Neutron Log dated 1-27-1996

- 31) Pull guns and rig down wireline company.
- 32) PU packer on tubing and run in hole to 3660'
- 33) RU Acid company with 2000 gallons 15% NEFE Anti-Sludge HCl acid containing H2S scavenger for 5000 ppm H2S + 1% by volume mutual solvent. Have 1200# graded rock salt and 10# brine on location for diversion.
- 34) Spot acid across perfs.
- 35) Pull packer to 3550' and reverse acid into tubing.
- Set packer.
- 37) Acidize perforations 3635-3659 in 4 equal stages using rock salt for diversion.
- 38) Flow and swab back load to check for productive capacity.
- 39) Release packer and retrieve RBP.

NOTE: Depending on productive capacity of Queen, it may be tested separately for up to 30 days.

NOTE: Additional perforations in Seven Rivers & Lower Yates may be added in a separate procedure for perforating and stimulation.

- 40) Run pumping equipment.
- 41) Test well and stabilize
- 42) As soon as well stabilizes, perform scale scale squeeze.