Form 3160-5 (April 2004)

UNITEDSTATES

FORMAPPROVED OM B No. 1004-0137

	DEPARTMENT OF THE BUREAU OF LAND MAN		OCD HODDS		pires: March 31, 2007
	NOTICES AND RE		ars n 6 2010	5. Lease Serial	No.
Do not use the abandoned w	his form for proposals vell. Use Form 3160 - 3	to drill or to re-er (APD) for such pro	IN SOCO	5. If Indian, Al	lottee or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on reverse side.				7. If Unit or CA/Agreement, Name and/or No.	
1. Type of Well Oil Well	Gas Well X Other		_		
				8. Well Name Wyatt A Fe	/
 Name of Operator ConocoPhillips Compan 	y /			API Well N	
3a. Address 3b. PhoneNo. (include area code)				30-025-01	
3300 N "A" St. Bldg 6, Midland, TX 79705 (432)688-6913 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area Maljamar; Grayburg-San Andres	
F,33,17S,33E 1650 FNL 1650 FWL /				11. County or Parish, State	
1,55,175,552 1050114	10001 002				y, New Mexico
12. CHECK A	PPROPRIATE BOX(ES)TO) INDICATE NATUR	E OF NOTICE, REF	ORT, OR O	THER DATA
TYPE OF SUBMISSION		TYP	EOF ACTION		
	X Acidize	Deepen	Production (Start/	Resume)	Water Shut-Off
Notice of Intent	AlterCasing	FractureTreat	Reclamation		Well Integrity
X Subsequent Report	Casing Repair	New Construction	Recomplete		Othertubing repair
Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back	Temporarily Aban Water Disposal	don	
following completion of the ir	the work will be performed or provolved operations. If the operation inal Abandonment Notices shall be by for final inspection.)	n results in a multiple comp	letion or recompletion in	a new interval.	a Form 3160-4 shall be filed once
MI 6- 3 1/8 drill collars 10/7/2010 pick up 6 3 1 10/8/2010 RU power sw 10/11/2010 Set work-st 10/12/2010 RU hydrote packer, RD hydrotester charted results 10/13/2010 Pressure te	nit, MI 154 Jnts tubing f /8 drill collars and bit, T vivel, RU Laydown mac ring out, set production sters, tally tubing, pick of s lay down machine and est well to 585# for 30 m 1000 gals of acid + 1000	rom ITS, RU laydor TAG at 4427, drill to hine, clean out fill to tbg in up packer, TIH with d floor, NDBOP, HI nin, finished at 580#	o 4481, pulled abo to 4705 In tubing while hyd UWH, Load and to #, OCD Maxey Br	ove perfs rotesting, est casing own passe	assembled tubing, set to 550 psi, held for 30 n ed well and signed chart 10# brine, RD acid truck
Chart attached. 14. I hereby certify that the fore	againg is true and correct			ACC	EPTED FOR REC
Name (Printed/Typed)	egonig is true and confect	1			
		Title	Regulatory Specia	ali\$t	L
Brian D Maiorino				1	תוחת צייייי
Signature Signature	NE:		11/08/2010		Jec 7 2010 /s/JD Whitlock Jr
P	THIS SPACE FOR	Daté 12.		SE DI	/s/ JD Whitlock Jr
P		Daté 12.	ATE OFFICE U	- - , BU !	/s/JD Whitlock Jr REAU OF LAND MANAGEM CARL SRAD FIFLD OFFICE

certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereof.

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

