

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Energy, Minerals and Natural Resources

RECEIVED
JAN 06 2011
HOBBSDO

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-025-04026
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Northwest Eumort Unit
8. Well Number 127
9. OGRID Number 19111
10. Pool name or Wildcat Eumort Yates 7 Rivers Queen

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator **Rhombus Operating Co., Ltd.**

3. Address of Operator
P.O. Box 8316 Midland, TX 79708-8316

4. Well Location
Unit Letter **J** : **A80** feet from the **South** line and **1450** feet from the **East** line
Section **22** Township **19S** Range **36E** NMPM County **Lea**

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3752 AB

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☒ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: **TA** ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. 12/14/10 - Set CIBP @ 4020' (Top cert @ 4070) dump bail 35' cm + on top of plug. New PBD @ 3985'.
2. 12/15/10 - Circ well w/100 bbls ph- fluid. Test to 500#, OK. LD +sg. Test to 500#, OK.
3. 1/4/11 - Conduct T/A status Test w/OCD rec Mark Whitaker present. ~~Test~~ Press to 570# & held for 30 min w/no leakoff or gain. Test Good. Chart Attached.

Spud Date:

Rig Release Date:


This Approval of Temporary Abandonment Expires **7-4-2011**

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE **Tony Bunch** TITLE **Operations Manager** DATE **1/5/11**

Type or print name **Tony Bunch** E-mail address: **t48bunch@yahoo.com** PHONE: **575-370-4313**
For State Use Only

APPROVED BY: **[Signature]** TITLE **STAFF MGR** DATE **1-10-2011**
Conditions of Approval (if any):



TEST DATE
01-04-2011
BR 2221

CALB
10/2010
M&S Services
GRAPHIC CONTROLS CORPORATION
BUFFALO NEW YORK

Start 10/15/11
OED

Tony Bush
Rhombus

Rhombus Operator
30-025-04026
T/A TEST
RECEIVED
JAN 05 2011
HOBBS

End 10/15/11

6 A.M.

MIDNIGHT

6 P.M.