

NEW MEXICO ENERGY, MINERALS NATURAL RESOURCES DEPARTMENT

Susana Martinez Governor

Harrison H. Schmitt Cabinet Secretary-Designate

Daniel Sanchez Acting Division Director Oil Conservation Division

Field Inspection Program "Preserving the Integrity of Our Environment"

12-Jan-11

PROVIDENCE ENERGY SERVS' INC.-KELTON OP CORP

PO BOX 928

ANDREWS TX 79714

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION	DETAIL.	SECTION
INSLECTION	DDIAID	SECTION

SKELLY PENROSE B UNIT No.	028^{-}
---------------------------	-----------

G-5-23S-37E

30-025-10630-00-00

Inspection Date

Type Inspection

Inspector

Violation?

*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

01/12/2011 Routine/Periodic Mark Whitaker

Yes

No

4/17/2011

iMAW1101243427

Violations

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE BOND. Dry hole marker correct. Injection riser exposed west of marker needs to be cut off 2° below gound level and removed, concrete blocks and coils of power line on south side of location and sucker rod and debris around well head need to be removed. Contour location

on north and west side. 1st notice.

SKELLY PENROSE B UNIT No.029

Routine/Periodic

30-025-10637-00-00

Inspection

01/12/2011

Type Inspection Date

Inspector

Mark Whitaker

Violation? Yes

*Significant Non-Compliance? No

H-5-23S-37E

Corrective Action Due By: 4/17/2011

Inspection No.

iMAW1101244728

Violations

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE BOND. Dry hole marker correct. Injection riser exposed, needs to be cut off 2' below gound level and removed. Pumping unit base and concrete slabs on west side of location

need to be removed. Contour location on west side. 1st notice.

SKELLY PENROSE B UNIT No.018

A-5-23S-37E

No

30-025-10638-00-00

Inspection 01/12/2011

Type Inspection Date

Inspector

*Significant Violation? Non-Compliance?

Corrective Action Due By:

Inspection No.

Mark Whitaker

Yes

4/17/2011

iMAW1101245621

Violations

Surface Damage/Restoration

Routine/Periodic

Comments on Inspection:

DO NOT RELEASE BOND. Dry hole marker correct. Joint of tbg north of marker, two white posts east of marker, valve and flowline east of marker (if not active), and two partially buried drums east of marker need to be removed. 1st notice.

SKELLY PENROSE B UNIT No.059

P-8-23S-37E

30-025-10677-00-00

Corrective

Inspection Date

Type Inspection

Inspector

*Significant Non-Compliance?

Action Due By:

Inspection No.

01/12/2011

Routine/Periodic

Mark Whitaker

Violation? Yes

No

4/17/2011

iMAW1101246854

Violations

Surface Damage/Restoration

Comments on Inspection:

DO NOT RELEASE. Dry hole marker not correct. Should read 330 FSL & 330 FEL not 330 FSL & 330 FNL. Need to correct marker. Injection riser exposed east of marker needs to be cut off 2' below gound level and removed. Well sign need to be removed. Location should be contoured. 1st notice.

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well. Such a hearing may result in imposition of CIVIL PENALTIES for your violation of OCD rules.

Sincerely.

COMPLIANCE OFFICER

Hobbs OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

EMNRD
OIL CONSERVATION DIVISION
1625 N FRENCH DRIVE
HOBBS NM 88240



PROVIDENCE ENERGY SERVICES, INC dba KELTON OPERATING CORP. PO BOX 928 ANDREWS, TX 79714-0928