Submit I Copy To Appropriate District State of New Mexico	Form C-103		
District Energy, Minerals and Natural Resources	October 13, 2009		
1625 N. French Dr., Hobbs, NM 88240 District II	WELL API NO. 30-005-20474		
District II 1301 W. Grand Ave., Artesia, NM 882T0	5. Indicate Type of Lease		
District III 1000 Couth St. Enongin Dr.	STATE FEE		
1000 Rio Brazos Rd., Aztec, NM 874 AN 1 1 2011 District IV Santa Fe, NM 87505	6. State Oil & Gas Lease No.		
1220 S. St. Francis Dr., Santa Fe, NMBBSOCD	K-6795		
87505 SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name		
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Lovelady SWD		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	8. Well Number /		
1. Type of Well: Oil Well \Box Gas Well, \Box Other SWD \checkmark			
2. Name of Operator	9. OGRID Number		
Yates Petroleum Corporation	025575		
3. Address of Operator	10. Pool name or Wildcat		
105 South Fourth Street, Artesia, NM 88210	SWD; San Andres		
4. Well Location			
Unit Letter J : feet from the South line and	<u>1980</u> feet from the <u>East</u> line		
Section 31 Township 8S Range 33E	NMPM Chaves County		
11. Elevation (Show whether DR, RKB, RT, GR, etc.,			
4388'GR			
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data		
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:		
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DR			
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 📋 CASING/CEMEN	Т ЈОВ 🗌		
	X		
OTHER: OTHER: MIT	d give pertinent dates, including estimated date		
	d give pertinent dates, including estimated date		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an	d give pertinent dates, including estimated date		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Com- proposed completion or recompletion.	d give pertinent dates, including estimated date		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well.	d give pertinent dates, including estimated date		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb Original MIT attached.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb Original MIT attached.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to be was notified of MIT, no witness on location.		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb Original MIT attached.	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to be was notified of MIT, no witness on location.		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: Image: Image: Image: Structure Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to os was notified of MIT, no witness on location.		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: Image: Image: Image: Structure Rig Release Date:	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to be was notified of MIT, no witness on location.		
OTHER: □ OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133". Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE Current of the structure of the test of my knowledg	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to os was notified of MIT, no witness on location. e and belief.		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Regulatory Compliance Type or print name Tina Huerta E-mail address: tina@yatespetroleur	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to os was notified of MIT, no witness on location. e and belief.		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Regulatory Compliance Type or print name Tina Huerta For State Use Only Tina Huerta	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to os was notified of MIT, no witness on location. e and belief. <u>Supervisor</u> DATE <u>January 10, 2011</u> <u>n.com</u> PHONE: <u>575-748-4168</u>		
OTHER: OTHER: MIT 13. Describe proposed or completed operations. (Clearly state all pertinent details, an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion. 12/7/10 – Rigged up. Bled well down and unflanged well. 12/8/10 – Pumped 50 bbls hot water down tubing to finish cleaning tubing. 12/15/10 – Bled well down. TIH with 126 jts and circulated fluid and ND BOP. Set AS-1 540 psi for 30 min, held good. 2-7/8" L-80 tubing at 4133'. Sylvia Dickey NMOCD-Hobb Original MIT attached. Spud Date: Rig Release Date: I hereby certify that the information above is true and complete to the best of my knowledg SIGNATURE TITLE Regulatory Compliance Type or print name Tina Huerta E-mail address: tina@yatespetroleur	d give pertinent dates, including estimated date mpletions: Attach wellbore diagram of packer at 4127' and flanged well up. Tested to os was notified of MIT, no witness on location. e and belief.		

C (F	Ingel
oval (if any).	0



NOEL JOEC New Mexico Energy, Minerals and Natural Resources Department

Bill Richardson Governor

Jim Noel Cabinet Secretary Karen W. Garcia Deputy Cabinet Secretary

DEC 0 6 2010

02-Dec-10

PRODUCTION DEPARTMENT RECEIVED

YATES PETROLEUM CORPORATION 105 S 4TH ST ARTESIA NM 88210-



DEC 06 2010

YPC

MAIL ROOM

WADE LEEROY



30-005-20474-00-00

LETTER OF VIOLATION and SHUT-IN DIRECTIVE **Failed Mechanical Integrity Test**

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section. The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well(s) must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that the well(s) will be retested so the test may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

LOVELADY SWD No.001

Completed	
1-15-11	

			Active Salt Water Disposal We	ell	J-31-8S-33E
īd	Test Date:	12/1/2010	Permitted Injection PSI:	Actual PSI:	
in a	Test Reason:	5-year Test	Test Result: F	Repair Due:	3/6/2011
•	Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE	
	Comments on	MIT: WELLWOULD NOT H NMOCD RULE 19.15.2	HOLD PRESSURE; FAILED PT *****OPER 26.11*****		
S	TATE 3 SWI) No.001		30-0	25-25686-00-00
			Active Salt Water Disposal We	ell	G-3-9S-32E
	Test Date:	12/1/2010	Permitted Injection PSI;	Actual PSI:	
	Test Reason:	Annual IMIT	Test Result: F	Repair Due:	3/6/2011
	Test Type:	Bradenhead Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
	Comments on I	BHT*** OPERATOR I	# PRESSURE DID NOT ATTEMPT TO BL N VIOLATION OF NMOCD RULE 19.15.2	EED DOWN: W	
Т	ENNECO SV	VD No.001			25-25762-00-00
			Active Salt Water Disposal We		P-2-11S-34E
	Test Date:	12/1/2010	Permitted Injection PSI:	Actual PSI:	1 2 110 ./12
	Test Reason:	5-year Test	Test Result: F	Repair Due:	3/6/2011
	Test Type:	Std. Annulus Pres. Test	FAIL TYPE: Other Internal Failure	FAIL CAUSE:	
	Commonte on I	MT. WELL WOLLD NOT L			

WELL WOULD NOT LOAD; USED 297 BBLS OF FLUID WOULD NOT LOAD TO PRESSURE **Comments on MIT:** UP FOR TEST; ****INFORMED OPERATOR TO SHUT WELL IN UNTIL REPAIRS ARE PERFORMED AND APPROVED***OPERATOR IN VIOLATION OF NMOCD RULE 19.15.26.11***

