Submit 3 Copies To Appropriate District Office District I 1625 N. French Dr., Hobbs, NM 88246 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1300 Rio Brazos Rd., Aztec, NM 87410 District IV 1000 Rio Brazos Rd., Aztec, NM 87410 District IV 1220 South St. Francis Dr. 1220 South St. 1220 S		Form C-103
		June 19, 2008 VELL API NO.
		. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410 District IV		STATE FEE X . State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM  87505 CLDUDDX NOTICES AND DEPODETS ON WELLS		Y
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		. Lease Name or Unit Agreement Name
1. Type of Well:     □Oil Well     □ Gas Well     ☑ Other: WSW       2. Name of Operator		. Well Number 010
Apache Corporation		73 /
3. Address of Operator 303 Veterans Airpark Lane, Suite 3000 Midland, TX 79705		0. Pool name or Wildcat /SW; San Andres (96221)
4. Well Location		
Unit Letter L : 1880 feet from the South line and 760 feet from the West line		
Section 15         Township 21S         Range 37E         NMPM         County Lea           11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)         11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
3453' DF		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
	COMMENCE DRILLING OPNS. P AND A	
	CASING/CEMENT JOB	
	OTHER:	
<ol> <li>Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.</li> </ol>		
<ul> <li>While performing routine work on this well a leak was detected and Apache repaired as follows:</li> <li>10/21/2010 MIRUSU 10/22-25/2010 Make 8-5/8" scraper run. 10/26/2010 Isolate 8-5/8" csg leak.</li> <li>10/27/2010 RIH &amp; set RBP @ 1500'. Dump 20' sand on RBP. Set Btm Tbg @ 345'. 10/28/2010 Prep to cement.</li> <li>10/29/2010 Pump 33.5 bbl Class C cmt; circ cmt up 8-5/8". Pump 16.5 bbl cmt down 8-5/8"; circ cmt to surface.</li> <li>11/01-09/2010 DO cmt; repair csg leak; tag cmt @ 217'. DO cmt; Ret RBP; clean out fill to top of liner.</li> <li>11/10-15/2010 CO 5-1/2" liner; begin swab. 11/16/2010 Swab</li> <li>11/17/2010 Acidize San Andres w/1260 bbl HCL, flush w/36 bbl 2% KCL.</li> <li>11/18/2010 Swab test; run pump in test.</li> <li>11/19/2010 Pump treatment</li> <li>11/23/2010 RIH w/ESP 11/24/2010 Install proper well head &amp; land tbg.</li> <li>11/29/2010 Rebuild well &amp; flowline - POP.</li> <li>11/30/2010 Adjust surface controls. 12/01/2010 Finish control adjustments; left well pumping.</li> </ul>		
Spud Date: 07/19/1951 Rig Release Da	te:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE Relsa Land TITLE Sr. Engr Tech DATE 01/24/2011		
Type or print name Reesa Holland       E-mail address: Reesa.Holland@apachecorp.com       PHONE: 432/818-1062         For State Use Only		
APPROVED BY:		
		la l
		Ŕ