Submit 2 Conica	To Appropriate District				E
Office					Form C-103 June 19, 2008
District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505				WELL API NO.	
District II 1301 W. Grand Ave. Artesia MM882107 A CONSERVATION DIVISION				<u>30-025-096</u>	
District III				5. Indicate Type of Lease	
1000 Rio Brazos Rd., Aztec, MAN 20 2011 Santa Fe, NM 87505				6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa-Fe, NM 87505				306443	/
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name or Unit	Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				Cooper Jal Unit	
PROPOSALS.)         1. Type of Well: Oil Well Gas Well Other Injector				8. Well Number 13	4
2. Name of Operator				9. OGRID Number 263848	
Resaca Operating Company /					
3. Address of Operator				10. Pool name or Wild	
2509 Maurice Road, Odessa, TX 79763				Jalmat; T-Y-7R: Langlie Mattix; 7R-Q-G	
4. Well Location					
Unit Letter       N       : 330       feet from the       South       line and       1650       feet from the       West       line					
Section 24 Township 24S Range 36E NMPM Lea County					
11. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3310' GL					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				-	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT JOB					
DOWNHOLE COMMINGLE					
OTHER:			OTHER: Clea	n Out & Acidize Injector	$\boxtimes$
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date					
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.					
<ol> <li>MIRU Pulling Unit and Above Ground Steel Pit.</li> <li>POOH w/ 2 3/8" tubing and 5 ½" x 2 3/8" Baker Model AD-1 Tension Packer.</li> <li>RIH w/ 4 ¾" Bit &amp; 4-3 ½" Drill Collars; tagged @ 3460'; RU Swivel &amp; cleaned out to 3570', circ'd clean.</li> <li>RIH, tagged @ 3570'; POOH w/ bit, laying down drill collars</li> <li>RIH w/ 2 3/8" Arrow Set 1-X Packer (Teflon coated); circulate annulus with inhibited packer fluid</li> <li>Set Packer @ 2950' (top perf @ 3031'); test annulus to 500 psig for 30 minutes, test good.</li> <li>Acidize perfs 3031'-3295', OH 3462'-3570', with 8500 gallons acid, dropping 15,700#'s salt.</li> <li>POOH, laying down work string; RIH w/ tbg &amp; tested tbg to 5000 psi, test good.</li> <li>Pressure tested annulus to 520 psi w/ Chart Recorder for 30 min., test good.</li> <li>Place well on Injection at approximately 300 bwpd; Maximum permitted injection pressure is 820 psig.</li> <li>RDMO Pulling Unit, cleaned location, cleaned and disposed of pit fluids.</li> <li>* MIT Chart witnessed &amp; signed by NMOCD Representative Mark Whitaker</li> </ol>					
Spud Date:	1/10/11	Rig Release Da	te:	/18/11	
	· · · · · · · · · · · · · · · · · · ·				
I hereby certify that the information above is true and complete to the best of my knowledge and belief.					
SIGNATURE					
Type or print r	ame Melanie Reyes	E-mail address: 1	nelanie.reves@res	acaexploitation.com PHC	NE: <u>(43</u> 2)580-8500
For State Use Only					
APPROVED BY:					

